



REV: 1.1

IDE

MON

CPU

Jumper that connects POWER_OK with /RESET
(CPU in slot A)

ATX POWER CONNECTOR

RESET