CPU02CMI - 2K ROM - GAL Selection Table.

Туре	I/O	G1 - Standard card	G1 - Standard card	G2 - All cards	Programmer
		11MHz & 12 MHz	8MHz & 10MHz		
GAL16V8A-15LP	2	X	Х	CMI_2	1, 2, 3, 4
GAL16V8B-15LP	1	Х	Х	CMI_2	1, 2, 3, 4
GAL16V8D-15LP	1	Х	Х	CMI_2	1, 2, 3, 4
GAL16V8D-25LP	1	Х	Х	CMI_2	1, 2, 3, 4
GAL22V10B-15LP	3	CMI-3_1	CMI_1	X	1, 2, 3, 4
GAL22V10D-15LP	3	CMI-3_1	CMI_1	X	1, 2, 3, 4
ATF16V8B-15PC	1	X	X	ATF-CMI_2	2, 3, 1, 4
ATF16V8B-25PC	1	X	X	ATF-CMI_2	2, 3, 1, 4
ATF16V8BQL-15PC	1	X	X	ATF-CMI_2	2, 3, 1, 4
ATF22V10B-15PC	1	ATF-CMI-3_1	ATF-CMI_1	X	2, 3, 1, 4
ATF22V10C-15PC	5	ATF-CMI-3_1	ATF-CMI_1	X	2, 3, 1, 4
ATF22V10CQZ-20PC	5	ATF-CMI-3_1	ATF-CMI_1	X	2, 3, 1, 4
PALCE16V8-15PC	1	X	X	CMI_2	2, 3, 4
PALCE16V8-25PC	1	X	X	CMI_2	2, 4, 3
PALCE16V8H-15PC/4	4	X	X	CMI_2	2, 3, 4
PALCE16V8H-25PC	4	X	X	CMI_2	2, 4, 3
PALCE16V8Q-15PC/4	4	X	X	CMI_2	2, 3, 4
PALCE22V10H-15PC/4	4	CMI-3_1	CMI_1	Х	2, 3, 4
PALCE22V10H-25PC/4	4	CMI-3_1	CMI_1	Х	2
PALCE22V10Q-25PC	4	CMI-3_1	CMI_1	Х	2

Tested Any open field means not used/tested First nr prefered

I/O: 1 = I/O 50K pull up
2 = I/O No pull up
3 = I/O Active pull up
4 = 100K|50K|No pull up
5 = I/O Pin keeper

Programmer: 1 = Xgpro TL866ll Plus, Sw 12.90 - Fw 04.2.132
2 = GALEP-4, Galep32 Version 1.20.4
3 = TOP2013, Sw Topall 8.92 - Fw 6.30
4 = TOP3002, Sw Topall 9.21 - Fw 6.93
5 = TOP3100, Sw Topall 8.92 - Fw 6.02

Remarks: I/O type 4 depending on device suffix, /4 = 100K, /5 = 50K, otherwise NO pull-up.

I/O type 2, 4 and 5 may need a pull-up on floating input pins.

Some ATF16V8B had errors on the TL866II Plus but not on the GALEP-4.

Do select the full name in the programmer A, B, C, D, H, Q, or CQZ, BQL version!

Otherwise you will get programming errors!

TOP family also select the correct speed -15 or -25 and /4 or /5! Check Position Tab!

Also read 'Documents\PLD and Programmers Info.pdf'.

Also tested a mix ATF / GAL / PALCE and -15 / -25