

The 1e mount is a 2.5" SATA HD.

2x M2.5x12
4x M2.5 nut



^ CG100 ^ MCA004 ^ SATA HD

4x M3x10
4x hex bus >



2.5" HDD Adapter ^ ^ MCA004 ^ SATA HD


4x M3x10



2.5" HDD Adapter ^ ^ MCA004 ^ SATA HD

4x M3x10

The 2e mount is a SDSATAVH0.




2x M3x10
2x M4 flat washer
2x M3 nut

2.5" HDD Adapter ^

^ MCA004

^ SDSATAVH0

The 3e mount is a Sintech CF.



2x M2.5x7
2x rubber
2x M2.5 nut

2.5" HDD Adapter ^ ^ MCA004 ^ Sintech CF

The 4e mount is a SDSATAVH0 + Sintech CF.


Side1:



2x M2.5x16
2x M2.5 nut spacer
2x M2.5 nut

2.5" HDD Adapter ^ ^MCA004 ^ SDSATAVH0

Side2:



2x M2.5x16
2x M2.5 nut spacer
1x M3 flat washer
2x M2.5 nut

2.5" HDD Adapter ^ ^MCA004 ^Sintech CF

Option:

2x M2.5x16
2x M2.5 nut
2x M2.5 nut



^ CG100 ^ MCA004
Connect the 3 devices with 44pin cable.