APPLIED TECHNICAL SERVICES, INCORPORATED

1405 Columbia Nitrogen Drive, Augusta, Georgia 30901 • (706) 823-0020 Fax (706) 823-0029 • www.atslab.com

White Light Intensity Verification

(Minimum of 100 fc (1000 Lx) is required at the surface)

White Light Source	
Make	STREAMLIGHT
Model	ProTac 2AA
Battery Quantity & Type	2AA -Fully Charged

White Light Meter Used For Verification	
ATS Asset #	1328
Calibration Date	7/11/22
Calibration Due Date	7/11/23

White Light Intensity: 431fc @ 12 inches (Low Setting)
1428fc @ 12 inches (High Setting)

- A calibrated white light meter shall be used to verify the intensity of the white light source. Measure and record the intensity in foot candles at the distance between the light source and the meter.

NOTE: A minimum of 100 fc is required at the surface of the inspection, but it is recommended that the white light intensity be measured at 24" or greater as the distance listed on this form will be the maximum distance allowed during examinations.

Performed By: JOSH DUPONT: ASNT LEVEL II VT

Date: 7/27/22

QC Manager -

Authorized Inspector - 7/27/22

This report may not be reproduced except in full without the written approval of ATS. If the method used is a customer provided, non-standard test method, ATS does not assume responsibility for validation of the method.