SPI slave with single port RAM

Teammates:

Abdulrahman Mohammad
Abdelrahman Ahmed Sayed

Under Supervision of:
Eng. Kareem Waseem

Snippets from the waveforms captured from QuestaSim

1_testing synchronous reset



2_testing read address



3_what was in the address



4_testing read data



5_test write address



6_testing write data



7_what we wrote in TB is written in the address we determined



Questa Lint



VIVADO

(* fsm_encoding = "gray" *)

Schematic elaboration



Schematic Synthesis





Encoding from report

State	New Encoding	Previous Encoding
IDLE	000	000
CHK_CMD	001	001
WRITE	011	010
READ_ADD	010	100
READ_DATA	111	011

Timing report

rts | Design Runs | Timing ×

Design Timing Summary

Setup		Hold		Pulse Width	
Worst Negative Slack (WNS):	5.445 ns	Worst Hold Slack (WHS):	0.142 ns	Worst Pulse Width Slack (WPWS):	4.500 ns
Total Negative Slack (TNS):	0.000 ns	Total Hold Slack (THS):	0.000 ns	Total Pulse Width Negative Slack (TPWS):	0.000 ns
Number of Failing Endpoints:	0	Number of Failing Endpoints:	0	Number of Failing Endpoints:	0



orts | Design Runs | Timing ×

Intra-Clock Paths - sys_clk_pin - Setup

Name	Slack	Levels	Routes	High Fanout	From	To	Total Delay	Logic Delay	Net Delay	Requirement
Path 1	5.445	2	3	1	R1/mem_reg/CLKBWRCLK	S1/MISO_reg/D	4.404	2.702	1.702	10.0



Tcl Console | Messages | Log | Reports | Design Runs | Timing ×

General Information
Timer Settings
Design Timing Summary

Intra-Clock Paths - sys_clk_pin - Setup

Name	Slack	Levels	Routes	High Fanout	From	To	Total Delay	Logic Delay	Net Delay	Requirem
Path 1	5.445	2	3	1	R1/mem_reg/CLKBWRCLK	S1/MISO_reg/D	4.404	2.702	1.702	
Path 2	6.978	1	2	3	S1/rx_data_reg[9]/C	R1/mem_reg/WEA[0]	2.310	0.751	1.559	

Implementation

Hierarchy

Name	Slice LUTs (20800)	Slice Registers (41600)	Slice (8150)	LUT as Logic (20800)	LUT Flip Flop Pairs (20800)	Block RAM Tile (50)	Bonded IOB (106)	BUFGCTRL (32)
SPI_w_RAM	28	29	9	28	17	0.5	5	1
R1 (RAM)	3	9	3	3	0	0.5	0	0
S1 (SPI_slave)	25	20	9	25	16	0	0	0

Design Timing Summary

Setup		Hold		Pulse Width	
Worst Negative Slack (WNS):	5.578 ns	Worst Hold Slack (WHS):	0.055 ns	Worst Pulse Width Slack (WPWS):	4.500 ns
Total Negative Slack (TNS):	0.000 ns	Total Hold Slack (THS):	0.000 ns	Total Pulse Width Negative Slack (TPWS):	0.000 ns
Number of Failing Endpoints:	0	Number of Failing Endpoints:	0	Number of Failing Endpoints:	0
Total Number of Endpoints:	81	Total Number of Endpoints:	81	Total Number of Endpoints:	32

All user specified timing constraints are met.

Device:



(* fsm_encoding = "one_hot" *)

Elaborator



Schematic Synthesis:



Encoding Report:

State	New Encoding	Previous Encoding
IDLE	00001	000
CHK_CMD	00010	001
WRITE	00100	010
READ_ADD	01000	100
READ_DATA	10000	011

Timing report:

Design Timing Summary

Setup		Hold		Pulse Width	
Worst Negative Slack (WNS):	5.898 ns	Worst Hold Slack (WHS):	0.142 ns	Worst Pulse Width Slack (WPWS):	4.500 ns
Total Negative Slack (TNS):	0.000 ns	Total Hold Slack (THS):	0.000 ns	Total Pulse Width Negative Slack (TPWS):	0.000 ns

Critical path



Implementation:

Reports | Design Runs | Power | Methodology | Timing | **Utilization** ×

Hierarchy

Name	Slice LUTs (20800)	Slice Registers (41600)	Slice (8150)	LUT as Logic (20800)	LUT Flip Flop Pairs (20800)	Block RAM Tile (50)	Bonded IOB (106)	BUFGCTRL (32)
N SPI_w_RAM	30	31	10	30	20	0.5	5	1
R1 (RAM)	3	9	4	3	0	0.5	0	0
S1 (SPI_slave)	27	22	9	27	19	0	0	0

Design Timing Summary

Setup		Hold		Pulse Width	
Worst Negative Slack (WNS):	5.414 ns	Worst Hold Slack (WHS):	0.047 ns	Worst Pulse Width Slack (WPWS):	4.500 ns
Total Negative Slack (TNS):	0.000 ns	Total Hold Slack (THS):	0.000 ns	Total Pulse Width Negative Slack (TPWS):	0.000 ns

(* fsm_encoding = "sequential" *)

Synthesis Schema:



Encoding report

State	New Encoding	Previous Encoding
IDLE	000	000
CHK_CMD	001	001
WRITE	010	010
READ_ADD	011	100
READ_DATA	100	011

Timing report:

Design Runs | Timing

Design Timing Summary

Setup		Hold		Pulse Width	
Worst Negative Slack (WNS):	5.682 ns	Worst Hold Slack (WHS):	0.142 ns	Worst Pulse Width Slack (WPWS):	4.500 ns
Total Negative Slack (TNS):	0.000 ns	Total Hold Slack (THS):	0.000 ns	Total Pulse Width Negative Slack (TPWS):	0.000 ns



Messages | Log | Reports | Design Runs | Timing

Intra-Clock Paths - sys_clk_pin - Setup

Name	Slack	Levels	Routes	High Fanout	From	To	Total Delay	Logic Delay	Net Delay	Requ
Path 1	5.682	2	3	1	R1/mem_reg/CLKBWRCLK	S1/MISO_reg/D	4.167	2.702	1.465	
Path 2	6.978	1	2	3	S1/rx_data_reg[9]/C	R1/mem_reg/WEA[0]	2.310	0.751	1.559	
Path 3	6.978	1	2	3	S1/rx_data_reg[9]/C	R1/mem_reg/WEA[1]	2.310	0.751	1.559	
Path 4	7.067	1	2	3	S1/rx_data_reg[9]/C	R1/mem_reg/ENBWREN	2.310	0.751	1.559	

Implementation

Reports | Design Runs | Power | Methodology | Timing | Utilization

Hierarchy

Name	Slice LUTs (20800)	Slice Registers (41600)	Slice (8150)	LUT as Logic (20800)	LUT Flip Flop Pairs (20800)	Block RAM Tile (50)	Bonded IOB (106)	BUFGCTRL (32)
SPI_w_RAM	29	29	9	29	19	0.5	5	1
R1 (RAM)	2	9	3	2	0	0.5	0	0
S1 (SPI_slave)	27	20	8	27	19	0	0	0

Design Runs | Power | Methodology | Timing | Utilization

Design Timing Summary

Setup		Hold		Pulse Width	
Worst Negative Slack (WNS):	5.503 ns	Worst Hold Slack (WHS):	0.044 ns	Worst Pulse Width Slack (WPWS):	4.500 ns
Total Negative Slack (TNS):	0.000 ns	Total Hold Slack (THS):	0.000 ns	Total Pulse Width Negative Slack (TPWS):	0.000 ns
Number of Failing Endpoints:	0	Number of Failing Endpoints:	0	Number of Failing Endpoints:	0



(* fsm_encoding = "johnson" *)

Synthesis schema



Encoding Report:

State	New Encoding	Previous Encoding
IDLE	000	000
CHK_CMD	100	001
WRITE	110	010
READ_ADD	111	100
READ_DATA	011	011

Timing report

Design Timing Summary

Setup		Hold		Pulse Width	
Worst Negative Slack (WNS):	5.445 ns	Worst Hold Slack (WHS):	0.142 ns	Worst Pulse Width Slack (WPWS):	4.500 ns
Total Negative Slack (TNS):	0.000 ns	Total Hold Slack (THS):	0.000 ns	Total Pulse Width Negative Slack (TPWS):	0.000 ns



Design Runs | Timing

Intra-Clock Paths - sys_clk_pin - Setup

Name	Slack	Levels	Routes	High Fanout	From	To	Total Delay	Logic Delay	Net Delay	Requireme
Path 1	5.445	2	3	1	R1/mem_reg/CLKBWRCLK	S1/MISO_reg/D	4.404	2.702	1.702	1(
Path 2	6.978	1	2	3	S1/rx_data_reg[9]/C	R1/mem_reg/WEA[0]	2.310	0.751	1.559	1(

Implementation

Reports | Design Runs | Power | Methodology | Timing | Utilization

Hierarchy

Name	Slice LUTs (20800)	Slice Registers (41600)	Slice (8150)	LUT as Logic (20800)	LUT Flip Flop Pairs (20800)	Block RAM Tile (50)	Bonded IOB (106)	BUFGCTRL (32)
SPI_w_RAM	29	29	10	29	18	0.5	5	1
R1 (RAM)	3	9	4	3	0	0.5	0	0
S1 (SPI_slave)	26	20	9	26	17	0	0	0

Design Timing Summary

Setup		Hold		Pulse Width	
Worst Negative Slack (WNS):	5.635 ns	Worst Hold Slack (WHS):	0.044 ns	Worst Pulse Width Slack (WPWS):	4.500 ns
Total Negative Slack (TNS):	0.000 ns	Total Hold Slack (THS):	0.000 ns	Total Pulse Width Negative Slack (TPWS):	0.000 ns



Massages: