

AUTO-SERV WORKSHOP

Production Automobile Service & Maintenance Center

OFFICIAL TAX INVOICE

Invoice Number: INV-2026-01005
Job Card Number: JC-2026-01003
Date Issued: 16/8/2026

Payment Status: PAID
Payment Method: UPI_DIRECT

CLIENT & VEHICLE DETAILS

Customer Name: Ketan dusare
Contact Phone: 8446131495
Vehicle: Yamaha R1
License Plate: MH23DJ3948

ITEMIZED WORKSHOP BREAKDOWN

Item Description	Qty	Unit Price	Total (INR [₹])
Labor Task: General Repair Task	1	Rs. 0.00	Rs. 0.00
Labor Task: General Repair Task	1	Rs. 0.00	Rs. 0.00
Labor Task: General Repair Task	1	Rs. 0.00	Rs. 0.00
Part: Front Gas Shock Absorber Strut (SHK-ABS-F)	1	Rs. 110.00	Rs. 110.00
Part: High-Output 120A Alternator Assembly (ALT-120A-HD)	1	Rs. 240.00	Rs. 240.00
Part: Front Gas Shock Absorber Strut (SHK-ABS-F)	1	Rs. 110.00	Rs. 110.00

Labor Subtotal: Rs. 0.00
Parts Subtotal: Rs. 460.00
GST / Tax (10%): Rs. 46.00
Grand Total: Rs. 506.00