





(a) 温度



$$q_{\text{in}} = h(T_{\infty} - \theta_s)$$



(b) 干基含水率



$$j_C = h_m(C_s - C_{\text{eq}})$$
$$C_{\text{eq}} := Y_{\infty}$$

中部剖切示意

$t = 1800 \text{ s}$