

Schematic, not to scale. Percentages: share of plant electricity in the audited reference month. Material flow (black), electricity (red), compressed air (blue).