




S1-T01 tee (defaults)  
VALID warnings=0




S1-T02 tee (fn=16)  
VALID warnings=0




S1-T03 tee\_oblique (defaults)  
VALID warnings=0




S1-T04 tee\_oblique (fn=16)  
VALID warnings=0




S1-T05 tee\_small (defaults)  
VALID warnings=0




S1-T06 tee\_small (fn=10)  
VALID warnings=0




S1-T07 tee\_large (defaults)  
VALID warnings=0




S1-T08 tee\_large (fn=30)  
VALID warnings=0




S1-T09 cross (defaults)  
VALID warnings=0




S1-T10 cross (fn=19)  
VALID warnings=0




S1-T11 boss\_plate (defaults)  
VALID warnings=0




S1-T12 boss\_plate (fn=26)  
VALID warnings=0




S2-T01 two\_bosses (defaults)  
VALID warnings=0




S2-T02 two\_bosses (fn=26)  
VALID warnings=0




S2-T03 pipe\_into\_face (defaults)  
VALID warnings=0




S2-T04 pipe\_into\_face (fn=19)  
VALID warnings=0




S2-T05 dome (defaults)  
VALID warnings=0




S2-T06 dome (fn=30)  
VALID warnings=0




S2-T07 hole\_plate (defaults)  
VALID warnings=0



S2-T08 hole\_plate (fn=22)  
VALID warnings=0




S2-T09 bevel\_boss (defaults)  
VALID warnings=0




S2-T10 bevel\_boss (fn=29)  
VALID warnings=0




S2-T11 cyl\_control (defaults)  
VALID warnings=0




S2-T12 cyl\_control (fn=30)  
VALID warnings=0




S3-T01 lbracket (defaults)  
VALID warnings=0




S3-T02 box\_step (defaults)  
VALID warnings=0




S3-T03 rib (defaults)  
VALID warnings=0




S3-T04 thin\_slab (defaults)  
VALID warnings=0




S3-T05 pocket (defaults)  
VALID warnings=0




S3-T06 chamfer\_box (defaults)  
VALID warnings=0




S3-T07 brush\_one\_edge (defaults)  
VALID warnings=0




S3-T08 cube\_control (defaults)  
VALID warnings=0




S3-T09 mixed\_fn (defaults)  
VALID warnings=0




S3-T10 rib\_into\_boss (defaults)  
VALID warnings=0



S3-T11 rib\_into\_boss (fn=26)  
VALID warnings=0



S3-T12 refused\_neighbour (defaults)  
VALID warnings=0



S4-T01 shallow\_crease (defaults)  
VALID warnings=0