




S1-T01 tee (defaults)  
VALID warnings=0




S1-T02 tee (fn=16)  
VALID warnings=0




S1-T03 tee\_oblique (defaults)  
VALID warnings=0




S1-T04 tee\_oblique (fn=16)  
VALID warnings=0




S1-T05 tee\_small (defaults)  
VALID warnings=0




S1-T06 tee\_small (fn=10)  
VALID warnings=0




S1-T07 tee\_large (defaults)  
VALID warnings=0




S1-T08 tee\_large (fn=30)  
VALID warnings=0




S1-T09 cross (defaults)  
VALID warnings=0




S1-T10 cross (fn=19)  
VALID warnings=0




S1-T11 boss\_plate (defaults)  
VALID warnings=0




S1-T12 boss\_plate (fn=26)  
VALID warnings=0




S2-T01 two\_bosses (defaults)  
VALID warnings=0




S2-T02 two\_bosses (fn=26)  
VALID warnings=0




S2-T03 pipe\_into\_face (defaults)  
VALID warnings=0




S2-T04 pipe\_into\_face (fn=19)  
VALID warnings=0




S2-T05 dome (defaults)  
VALID warnings=0




S2-T06 dome (fn=30)  
VALID warnings=0




S2-T07 hole\_plate (defaults)  
VALID warnings=0



S2-T08 hole\_plate (fn=22)  
VALID warnings=0




S2-T09 bevel\_boss (defaults)  
VALID warnings=0




S2-T10 bevel\_boss (fn=29)  
VALID warnings=0




S2-T11 cyl\_control (defaults)  
VALID warnings=0




S2-T12 cyl\_control (fn=30)  
VALID warnings=0




S3-T01 lbracket (defaults)  
VALID warnings=0




S3-T02 box\_step (defaults)  
VALID warnings=0




S3-T03 rib (defaults)  
VALID warnings=0




S3-T04 thin\_slab (defaults)  
VALID warnings=0




S3-T05 pocket (defaults)  
VALID warnings=0




S3-T06 chamfer\_box (defaults)  
VALID warnings=0




S3-T07 brush\_one\_edge (defaults)  
VALID warnings=0




S3-T08 cube\_control (defaults)  
VALID warnings=0




S3-T09 mixed\_fn (defaults)  
VALID warnings=0



S3-T10 rib\_into\_boss (defaults)  
VALID warnings=0




S3-T11 rib\_into\_boss (fn=26)  
VALID warnings=0




S3-T12 refused\_neighbour (defaults)  
VALID warnings=0


fillet bench -- sheet 4 of 4




S4-T01 shallow\_crease (defaults)  
VALID warnings=0




S4-T02 elbow\_big (defaults)  
VALID warnings=0



S4-T03 elbow\_crowded (defaults)  
VALID warnings=0




S4-T04 elbow\_curved\_endface (defaults)  
VALID warnings=2




S4-T05 elbow\_curved\_wall (defaults)  
VALID warnings=2




S4-T06 elbow\_dihedral120 (defaults)  
VALID warnings=0




S4-T07 elbow\_dihedral60 (defaults)  
VALID warnings=0




S4-T08 elbow\_facet\_endface (defaults)  
VALID warnings=0




S4-T09 elbow\_oblique50 (defaults)  
VALID warnings=0



S4-T10 elbow\_oblique75 (defaults)  
VALID warnings=0




S4-T11 elbow\_rot30 (defaults)  
VALID warnings=0




S4-T12 elbow\_thin\_arm (defaults)  
VALID warnings=2




fillet bench -- sheet 5: corner dispatch (labels measured from the dispatch echo)




S5-T01 lbracket [torus tube=2]  
front elbow (6,0,6) warnings=0




S5-T02 lbracket [torus tube=2]  
back elbow (6,30,6) mirrored warnings=0



S5-T03 box\_step [torus tube=2]  
front elbow (24,0,10) warnings=0




S5-T04 box\_step [torus tube=2]  
back elbow (24,40,10) mirrored warnings=0




S5-T05 rib [torus + saddle tube=4 saddle=4]  
rib end on plate (20,2,5,2,5) warnings=0




S5-T06 pocket [torus + tri-cap tube=4 capTri=12]  
pocket floor corner (12,12,-2) warnings=0




S5-T07 shallow\_crease [stock tube=0; min\_angle 25 tube=2]  
fold end face, ridge x=60 (60,0,16,.36) warnings=0




S5-T08 tee [flat ear-clip flat=2]  
cylinder junction (5,0,10) warnings=0




S5-T09 cross [tri-cap valleys capTri=8, flat=3]  
three-axis star (0,0,0) warnings=0



S5-T10 tee\_oblique [flat ear-clip flat=4]  
oblique junction (5,0,11.5) warnings=0




S5-T11 refused\_neighbour [saddle saddle=6]  
refused crease (7.5,4,7.44) + built bead warnings=0




S5-T12 mixed\_fn [centroid fan fan=4]  
48/10-facet junction (6,0,10) warnings=0


fillet bench -- sheet 6: torus-gate boundary (dispatch and mesh verdict both measured)




S6-T01 elbow\_oblique75 [canal tube=2]  
end face raked 15deg, crease meets it at 75deg  
VALID warnings=0



S6-T02 elbow\_oblique50 [canal tube=2]  
end face raked 40deg, crease meets it at 50deg  
VALID warnings=0




S6-T03 elbow\_dihedral60 [canal tube=2]  
60deg trough, square end face  
VALID warnings=0




S6-T04 elbow\_dihedral120 [canal tube=4]  
120deg trough (leaning wall), square end face  
VALID warnings=0




S6-T05 elbow\_curved\_endface [saddle=2 at stock (foot-clamped)]  
crease dies on a cylindrical end wall, 3 facets across  
VALID warnings=2




S6-T06 elbow\_curved\_wall [saddle=2 at stock, tube=2 at fn 16/64]  
cylindrical trough wall, arc crease  
VALID warnings=2




S6-T07 elbow\_facet\_endface [one of each: tube=1 coons=1]  
end face kinks 10deg exactly at the crease  
VALID warnings=0




S6-T08 elbow\_crowded [torus tube=2, not crowded out]  
arms 6 thick against 2R=5.8  
VALID warnings=0




S6-T09 elbow\_thin\_arm [saddle+fan, turn seat (was torus tube=2)]  
arm 3 thick against 2R=4  
VALID warnings=2



S6-T10 step\_notch [torus + tri-cap tube=3 capTri=11]  
inverse elbow: 2 concave + 1 convex  
VALID warnings=0



S6-T11 elbow\_rot30 [torus tube=2]  
control: square elbow rotated 30deg about z  
VALID warnings=0



S6-T12 elbow\_big [torus tube=2]  
control: bracket at 3x size and 3x radius  
VALID warnings=0