




S1-T01 tee (defaults)
VALID warnings=0




S1-T02 tee (fn=16)
VALID warnings=0




S1-T03 tee_oblique (defaults)
VALID warnings=0




S1-T04 tee_oblique (fn=16)
VALID warnings=0




S1-T05 tee_small (defaults)
VALID warnings=0




S1-T06 tee_small (fn=10)
VALID warnings=0




S1-T07 tee_large (defaults)
VALID warnings=0




S1-T08 tee_large (fn=30)
VALID warnings=0




S1-T09 cross (defaults)
VALID warnings=0




S1-T10 cross (fn=19)
VALID warnings=0




S1-T11 boss_plate (defaults)
VALID warnings=0




S1-T12 boss_plate (fn=26)
VALID warnings=0




S2-T01 two_bosses (defaults)
VALID warnings=0




S2-T02 two_bosses (fn=26)
VALID warnings=0




S2-T03 pipe_into_face (defaults)
VALID warnings=0




S2-T04 pipe_into_face (fn=19)
VALID warnings=0




S2-T05 dome (defaults)
VALID warnings=0




S2-T06 dome (fn=30)
VALID warnings=0




S2-T07 hole_plate (defaults)
VALID warnings=0



S2-T08 hole_plate (fn=22)
VALID warnings=0



S2-T09 bevel_boss (defaults)
VALID warnings=0




S2-T10 bevel_boss (fn=29)
VALID warnings=0




S2-T11 cyl_control (defaults)
VALID warnings=0




S2-T12 cyl_control (fn=30)
VALID warnings=0




S3-T01 lbracket (defaults)
VALID warnings=0




S3-T02 box_step (defaults)
VALID warnings=0




S3-T03 rib (defaults)
VALID warnings=0




S3-T04 thin_slab (defaults)
VALID warnings=0




S3-T05 pocket (defaults)
VALID warnings=0




S3-T06 chamfer_box (defaults)
VALID warnings=0




S3-T07 brush_one_edge (defaults)
VALID warnings=0




S3-T08 cube_control (defaults)
VALID warnings=0




S3-T09 mixed_fn (defaults)
VALID warnings=0



S3-T10 rib_into_boss (defaults)
VALID warnings=0




S3-T11 rib_into_boss (fn=26)
VALID warnings=0




S3-T12 refused_neighbour (defaults)
VALID warnings=0


fillet bench -- sheet 4 of 4




S4-T01 shallow_crease (defaults)
VALID warnings=0




S4-T02 elbow_big (defaults)
VALID warnings=0



S4-T03 elbow_crowded (defaults)
VALID warnings=0




S4-T04 elbow_curved_endface (defaults)
VALID warnings=2




S4-T05 elbow_curved_wall (defaults)
VALID warnings=2




S4-T06 elbow_dihedral120 (defaults)
VALID warnings=0




S4-T07 elbow_dihedral60 (defaults)
VALID warnings=2




S4-T08 elbow_facet_endface (defaults)
VALID warnings=0




S4-T09 elbow_oblique50 (defaults)
VALID warnings=0



S4-T10 elbow_oblique75 (defaults)
VALID warnings=0




S4-T11 elbow_rot30 (defaults)
VALID warnings=0




S4-T12 elbow_thin_arm (defaults)
VALID warnings=2


fillet bench -- sheet 5: corner dispatch (labels measured from the dispatch echo)




S5-T01 lbracket [torus tube=2]
front elbow (6,0,6) warnings=0




S5-T02 lbracket [torus tube=2]
back elbow (6,30,6) mirrored warnings=0



S5-T03 box_step [torus tube=2]
front elbow (24,0,10) warnings=0




S5-T04 box_step [torus tube=2]
back elbow (24,40,10) mirrored warnings=0




S5-T05 rib [torus + saddle tube=4 saddle=4]
rib end on plate (20,2,5,2,5) warnings=0




S5-T06 pocket [torus + tri-cap tube=4 capTri=12]
pocket floor corner (12,12,-2) warnings=0




S5-T07 shallow_crease [stock tube=0; min_angle 25 tube=2]
fold end face, ridge x=60 (60,0,16,.36) warnings=0




S5-T08 tee [flat ear-clip flat=2]
cylinder junction (5,0,10) warnings=0




S5-T09 cross [tri-cap valleys capTri=8, flat=3]
three-axis star (0,0,0) warnings=0



S5-T10 tee_oblique [flat ear-clip flat=4]
oblique junction (5,0,11.5) warnings=0




S5-T11 refused_neighbour [saddle saddle=6]
refused crease (7.5,4,7.44) + built bead warnings=0




S5-T12 mixed_fn [centroid fan fan=4]
48/10-facet junction (6,0,10) warnings=0


fillet bench -- sheet 6: torus-gate boundary (dispatch and mesh verdict both measured)




S6-T01 elbow_oblique75 [canal tube=2]
end face raked 15deg, crease meets it at 75deg
VALID warnings=0



S6-T02 elbow_oblique50 [canal tube=2]
end face raked 40deg, crease meets it at 50deg
VALID warnings=0




S6-T03 elbow_dihedral60 [canal tube=2]
60deg trough, square end face
VALID warnings=0




S6-T04 elbow_dihedral120 [canal tube=4]
120deg trough (leaning wall), square end face
VALID warnings=0




S6-T05 elbow_curved_endface [saddle=2 at stock (foot-clamped)]
crease dies on a cylindrical end wall, 3 facets across
VALID warnings=2




S6-T06 elbow_curved_wall [saddle=2 at stock, tube=2 at fn 16/64]
cylindrical trough wall, arc crease
VALID warnings=2




S6-T07 elbow_facet_endface [one of each: tube=1 coons=1]
end face kinks 10deg exactly at the crease
VALID warnings=0




S6-T08 elbow_crowded [torus tube=2, not crowded out]
arms 6 thick against 2R=5.8
VALID warnings=0




S6-T09 elbow_thin_arm [saddle+fan, turn seat (was torus tube=2)]
arm 3 thick against 2R=4
VALID warnings=2



S6-T10 step_notch [torus + tri-cap tube=3 capTri=11]
inverse elbow: 2 concave + 1 convex
VALID warnings=0



S6-T11 elbow_rot30 [torus tube=2]
control: square elbow rotated 30deg about z
VALID warnings=0



S6-T12 elbow_big [torus tube=2]
control: bracket at 3x size and 3x radius
VALID warnings=0