




S1-T01 tee (defaults)
VALID warnings=0




S1-T02 tee (fn=16)
VALID warnings=0




S1-T03 tee_oblique (defaults)
VALID warnings=0




S1-T04 tee_oblique (fn=16)
VALID warnings=0




S1-T05 tee_small (defaults)
VALID warnings=0




S1-T06 tee_small (fn=10)
VALID warnings=0




S1-T07 tee_large (defaults)
VALID warnings=0




S1-T08 tee_large (fn=30)
VALID warnings=0




S1-T09 cross (defaults)
VALID warnings=0




S1-T10 cross (fn=19)
VALID warnings=0




S1-T11 boss_plate (defaults)
VALID warnings=0




S1-T12 boss_plate (fn=26)
VALID warnings=0




S2-T01 two_bosses (defaults)
VALID warnings=0




S2-T02 two_bosses (fn=26)
VALID warnings=0




S2-T03 pipe_into_face (defaults)
VALID warnings=0




S2-T04 pipe_into_face (fn=19)
VALID warnings=0




S2-T05 dome (defaults)
VALID warnings=0




S2-T06 dome (fn=30)
VALID warnings=0




S2-T07 hole_plate (defaults)
VALID warnings=0



S2-T08 hole_plate (fn=22)
VALID warnings=0




S2-T09 bevel_boss (defaults)
VALID warnings=0




S2-T10 bevel_boss (fn=29)
VALID warnings=0




S2-T11 cyl_control (defaults)
VALID warnings=0




S2-T12 cyl_control (fn=30)
VALID warnings=0




S3-T01 lbracket (defaults)
VALID warnings=0




S3-T02 box_step (defaults)
VALID warnings=0




S3-T03 rib (defaults)
VALID warnings=0




S3-T04 thin_slab (defaults)
VALID warnings=0




S3-T05 pocket (defaults)
VALID warnings=0




S3-T06 chamfer_box (defaults)
VALID warnings=0




S3-T07 brush_one_edge (defaults)
VALID warnings=0




S3-T08 cube_control (defaults)
VALID warnings=0




S3-T09 mixed_fn (defaults)
VALID warnings=0




S3-T10 rib_into_boss (defaults)
VALID warnings=0



S3-T11 rib_into_boss (fn=26)
VALID warnings=0




S3-T12 refused_neighbour (defaults)
VALID warnings=0




S4-T01 shallow_crease (defaults)
VALID warnings=0


fillet bench -- sheet 5: corner dispatch (labels documented, not measured)




S5-T01 lbracket [torus]
front elbow (6,0,6) warnings=0




S5-T02 lbracket [torus]
back elbow (6,30,6) mirrored warnings=0



S5-T03 box_step [torus]
front elbow (24,0,10) warnings=0




S5-T04 box_step [torus]
back elbow (24,40,10) mirrored warnings=0




S5-T05 rib [torus]
rib end on plate (20,2.5,2.5) warnings=0




S5-T06 pocket [torus]
pocket floor corner (12,12,-2) warnings=0




S5-T07 shallow_crease [torus]
fold end face, ridge x=60 (60,0,16..36) warnings=0




S5-T08 tee [loft:T]
cylinder junction (5,0,10) warnings=0




S5-T09 cross [loft:star]
three-axis star (0,0,0) warnings=0



S5-T10 tee_oblique [loft:oblique]
oblique junction (5,0,11.5) warnings=0




S5-T11 refused_neighbour [loft:partial]
refused crease (7.5,4,7.44) + built bead warnings=0




S5-T12 mixed_fn [loft:curved]
48/10-facet junction (6,0,10) warnings=0


fillet bench -- sheet 6: torus-gate boundary (dispatch documented, not measured; mesh verdict measured)




S6-T01 elbow_oblique75 [loft:oblique-face]
end face raked 15deg, crease meets it at 75deg
VALID warnings=0




S6-T02 elbow_oblique50 [loft:oblique-face]
end face raked 40deg, crease meets it at 50deg
VALID warnings=0




S6-T03 elbow_dihedral60 [loft:non-square]
60deg trough, square end face
VALID warnings=0




S6-T04 elbow_dihedral120 [loft:non-square]
120deg trough (leaning wall), square end face
VALID warnings=0




S6-T05 elbow_curved_endface [loft:curved-face]
crease dies on a cylindrical end wall, 3 facets across
VALID warnings=0




S6-T06 elbow_curved_wall [loft:curved-wall]
cylindrical trough wall, arc crease
VALID warnings=0




S6-T07 elbow_facet_endface [loft or torus (grouping)]
end face kinks 10deg exactly at the crease
VALID warnings=0




S6-T08 elbow_crowded [torus (crowded)]
arms 6 thick against 2R=5.8
VALID warnings=0




S6-T09 elbow_thin_arm [refuse or crowd]
arm 3 thick against 2R=4
VALID warnings=0



S6-T10 step_notch [loft:inverse]
inverse elbow: 2 concave + 1 convex
VALID warnings=0



S6-T11 elbow_rot30 [torus]
control: square elbow rotated 30deg about z
VALID warnings=0



S6-T12 elbow_big [torus]
control: lbracket at 3x size and 3x radius
VALID warnings=0