Repair Estimate

Service Advisor

Jerry Pounders (228)

Prepared For Ruben SCHWARTZ

(555) 555-1234

Date 4/6/2015 5:17 PM 2009 SUBARU LEGACY OUTBACK VIN 4S4BP60C197317903 Mileage 62,000 RO# 142595

Service Name		Price
[Primary]: CST - C/S RATTLING NOISE. LAST TIME IT WAS A LOOSE HEAT SHIELD. CHECK AND ADVISE		0.00
[Primary]: FSC - DEFAULT		0.00
A/C Expansion Block/Orifice Tube GOOD PART BETTER PART BEST PART	100.00 200.00 300.00	100.00
A/T - Band Good Part Better Part Best Part	400.00 500.00 600.00	100.00
A/T - Accumulator		200.00
A/T - Band Control Solenoid Valve		200.00
A/T - Downshift Switch		200.00
A/T - Overdrive Relay		200.00
Printed on Apr	ril 06, 2015	
Quote expires on Apr	ril 06, 2015	

GOOD PART + Good Part
Subtotal 1500.00
Shop Charges 25.00
Tax 35.00
Total 1560.00

GOOD PART + Better Part

Subtotal 1600.00 Shop Charges 25.00 Tax 42.00 **Total 1667.00**

Subtotal 1700.00
Shop Charges 25.00
Tax 49.00

Total 1774.00

BETTER PART + Good Part
Subtotal 1600.00
Shop Charges 25.00
Tax 42.00

Total 1667.00

BETTER PART + E	Better Part	
Subtotal	1700.00	
Shop Charges	25.00	
Tax	49.00	
Total	1774.00	
Total	1774.00	
BETTER PART +	. Rost Part	
Subtotal	1800.00	
Shop Charges	25.00	
Tax	56.00	
<u>Total</u>	1881.00	
BEST PART +	Good Part	
Subtotal	1700.00	
Shop Charges	25.00	
Tax	49.00	
Total	1774.00	
BEST PART + Better Part		
Subtotal	1800.00	
Shop Charges	25.00	
Tax	56.00	
Total	1881.00	
	1001.00	
BEST PART + Best Part		
Subtotal	1900.00	
Shop Charges	25.00	
Tax	63.00	
_		
Total	1988.00	

Fordin Subaru

Fordin Subaru 6120 Saint Giles St, Suite 260 Raleigh NC 888-555-1234