
J1/J2 pins upwards

Other pins downwards



All passives

B = F405/415