


Pool Room — Four On Top


Six tables; four rounds and a center fifth on the north end



Inside the room at the southwest end, eye level, looking east toward the Main Entry



Overhead render



Service-flow diagram

In brief

- Four aligned rounds around a center fifth — one big social cluster that doubles as a tournament gallery facing the nearest table row.
- Wall two-tops flank every table row on both walls.
- The cluster runs deliberately tight, and the two-top by the kitchen door partially fronts it — both accepted.
- Cue room around the tables: most sides get about 60"; the shortest clearance is 56".

Pool Room — Four On Top — Turned


The same pattern with every table rotated sideways



Main Entry — two steps down, iron rails

wood door standing open


Inside the room at the southwest end, eye level, looking east toward the Main Entry



Overhead render

Pool Room — Four On Top — Turned

The same pattern with every table rotated sideways




Service-flow diagram

In brief

- Four tables in a block at the top, two at the bottom, all turned ninety degrees.
- Two-top bands ride the top wall, the seam between the clusters, and the bottom wall — every table has seating at arm's reach.
- FLAG: the rotated ends run tight side-to-side; the west and center aisles are the practical maximum.
- Cue room around the tables: most sides get about 47"; the shortest clearance is 47".

Pool Room — Four On Top — Turned Left


The turned pattern slid left




Main Entry — two steps down, iron rails

wood door standing open

Inside the room at the southwest end, eye level, looking east toward the Main Entry



Overhead render




Service-flow diagram

In brief

- Both columns slide toward the left wall: the whole east side becomes service and standing room with full end swings.
- FLAG: the west end swings run hard against the wall — the cost of the slide.
- Cue room around the tables: most sides get about 47"; the shortest clearance is 37".

Pool Room — Four On Top — Turned Right


The turned pattern slid right




Main Entry — two steps down, iron rails

wood door standing open

Inside the room at the southwest end, eye level, looking east toward the Main Entry



Overhead render




Service-flow diagram

In brief

- Both columns slide toward the right wall, as far as the chase and entry well allow; the west side becomes service and standing room with full end swings.
- FLAG: the east end swings run hard toward the wall — the cost of the slide.
- Cue room around the tables: most sides get about 47"; the shortest clearance is 37".

Pool Room — Center Line


Six tables turned sideways, end-to-end down the middle



Inside the room at the southwest end, eye level, looking east toward the Main Entry



Overhead render




Service-flow diagram

In brief


- Every table on display from the full-length side aisles.
- The service lane runs inboard, between the table ends and the east wall tops — the wall lane pinched.
- Side-to-side swings between neighbours run tight; the table ends get full room.
- Cue room around the tables: most sides get about 74"; the shortest clearance is 55".

Pool Room — East Line + West Lounge


Tables single-file on the east; six aligned rounds west



Inside the room at the southwest end, eye level, looking east toward the Main Entry



Overhead render




Service-flow diagram

In brief


- Six rounds in one line down the west side, each on its table's centerline.
- FLAG: the southernmost round narrows the Emergency Exit approach — the walk bends around its chairs.
- Every delivery crosses the table line — hospitality sits opposite the doors.
- Cue room around the tables: most sides get about 55"; the shortest clearance is 55".

Pool Room — East Line — Shifted Down


The east line slid toward the bottom wall



Inside the room at the southwest end, eye level, looking east toward the Main Entry



Overhead render



Service-flow diagram

In brief


- The top table rejoins the straight line and every compromise at the entry end dissolves — all six rounds sit on their centerlines at the wall, clear of the exit approach.
- FLAG: the bottom table's end swing runs tight against the bottom wall — the cost of the slide.
- Cue room around the tables: most sides get about 55"; the shortest clearance is 43".

Pool Room — West Line + Wall Rounds


Tables single-file west; a round beside every table east



Inside the room at the southwest end, eye level, looking east toward the Main Entry



Overhead render



Service-flow diagram

In brief


- Every table gets its own five-foot round at matching height — all six, per the brief.
- FLAG: the southernmost round crowds the Main Entry approach beside the stair rail.
- FLAG: one round sits partially in front of the kitchen door — accepted to keep its table paired.
- Cue room around the tables: most sides get about 55"; the shortest clearance is 39".

Pool Room — West Line — Shifted Down

The west line slid toward the bottom wall




Inside the room at the southwest end, eye level, looking east toward the Main Entry



Overhead render

Pool Room — West Line — Shifted Down

The west line slid toward the bottom wall



Service-flow diagram

In brief

- The entry end frees up: the sixth round reaches the east wall like the rest instead of pulling far inboard (its chairs still graze the approach corner).
- The third round pulls inboard to keep the kitchen door's wall approach clear; kitchen service still threads a squeeze between two rounds' chairs.
- FLAG: the bottom table's end swing runs tight against the bottom wall — the cost of the slide.
- Cue room around the tables: most sides get about 55"; the shortest clearance is 41".