
PAS 3-D Gain Factors



DATASET #1 (line: Shaded Uncertain Dataset, width=1.0; color: 220,220,220)

DATASET #2 (line: Shaded Uncertain Dataset, width=1.0; color: 192,192,192) 2.5%-97.5%

DATASET #3 (line: Shaded Uncertain Dataset, width=1.0; color: 0,255,0) 16%-84%

DATASET #4 (line: Solid, width=2.0; color: 128,128,128)

3-D Gains Mean

DATASET #5 (line: Dashed, width=2.0; color: 0,0,0)