REPAIR QUOTATION

AutoCare Works Pte Ltd

WORKSHOP	AutoCare Works Pte Ltd	**UEN**	201923477K
DATE OF QUOTATION	20/08/2026	**VALID UNTIL**	31/12/2026
VEHICLE REGISTRATION NO.	LSV8062G	**CHASSIS NO.**	JHMFC1F50PM000928
MAKE / MODEL	Honda Civic	**ENGINE CAPACITY (CC)**	1498
CLAIM REFERENCE	CLM-2026-CASE229		

WORKSHOP ADDRESS

No. 12 Tuas Crescent, Singapore 639588

PART C ITEMISED QUOTATION

Part No.	Description	Cat.	Parts	Hrs	Labour	Paint	Amount
P-5121	Front Bumper - replacement panel, primed and fitted	PANEL_REPLACE	1,958	3.5	520	702	3,179.25
P-9396	Front Left Headlamp - replacement assembly, fitted and sealed	ASSEMBLY_REPLACE	1,593	1.8	267	0	1,860.30
P-0001	Workshop consumables, panel adhesive, fasteners, solvent	CONSUMABLE	180	0.0	0	0	180.00

Subtotal (before GST)	$ 5,219.55
GST (9%)	$ 469.76
TOTAL (GST inclusive)	**$ 5,689.31**

TERMS AND CONDITIONS

Quotation covers labour, parts and refinishing only; excludes paint materials consumed on a per-panel basis beyond the lines above. Any additional damage discovered on disassembly requires a supplementary quotation before work proceeds. This quotation does not constitute an instruction to repair. All prices in SGD, GST inclusive where stated.

AUTHORISED SIGNATORY / DATE