REPAIR QUOTATION

Bedok Motorworks Pte Ltd

WORKSHOP	Bedok Motorworks Pte Ltd	**UEN**	200801155W
DATE OF QUOTATION	25/07/2026	**VALID UNTIL**	31/12/2026
VEHICLE REGISTRATION NO.	JFD7741R	**CHASSIS NO.**	KNAP4A19A8T602255
MAKE / MODEL	Kia Cerato	**ENGINE CAPACITY (CC)**	1598
CLAIM REFERENCE	CLM-2026-CASE381		

WORKSHOP ADDRESS

31 Bedok North Street 4, Singapore 469847

PART C ITEMISED QUOTATION

Part No.	Description	Cat.	Parts	Hrs	Labour	Paint	Amount
P-3730	Windscreen - replacement glass, fitted and sealed	GLASS_REPLACE	1,323	1.5	223	0	1,545.75
P-5121	Front Bumper - replacement panel, primed and fitted	PANEL_REPLACE	1,958	3.5	520	702	3,179.25
P-1632	Rear Bumper - replacement panel, primed and fitted	PANEL_REPLACE	1,863	3.5	520	675	3,057.75
P-9396	Front Left Headlamp - replacement assembly, fitted and sealed	ASSEMBLY_REPLACE	1,593	1.8	267	0	1,860.30
P-0001	Workshop consumables, panel adhesive, fasteners, solvent	CONSUMABLE	180	0.0	0	0	180.00

Subtotal (before GST)	$ 9,823.05
GST (9%)	$ 884.07
TOTAL (GST inclusive)	**$ 10,707.12**

TERMS AND CONDITIONS

Quotation covers labour, parts and refinishing only; excludes paint materials consumed on a per-panel basis beyond the lines above. Any additional damage discovered on disassembly requires a supplementary quotation before work proceeds. This quotation does not constitute an instruction to repair. All prices in SGD, GST inclusive where stated.

AUTHORISED SIGNATORY / DATE