REPAIR QUOTATION

AutoCare Works Pte Ltd

WORKSHOP	AutoCare Works Pte Ltd	**UEN**	201923477K
DATE OF QUOTATION	21/04/2026	**VALID UNTIL**	31/12/2026
VEHICLE REGISTRATION NO.	WQX3177L	**CHASSIS NO.**	KM8J33CA4KU884210
MAKE / MODEL	Hyundai Tucson	**ENGINE CAPACITY (CC)**	1598
CLAIM REFERENCE	CLM-2026-CASE410		

WORKSHOP ADDRESS

No. 12 Tuas Crescent, Singapore 639588

PART C ITEMISED QUOTATION

Part No.	Description	Cat.	Parts	Hrs	Labour	Paint	Amount
P-9396	Front Left Headlamp - replacement assembly, fitted and sealed	ASSEMBLY_REPLACE	2,242	1.8	376	0	2,618.20
P-5145	Rear Window - replacement glass, fitted and sealed	GLASS_REPLACE	1,634	1.5	314	0	1,947.50
P-0001	Workshop consumables, panel adhesive, fasteners, solvent	CONSUMABLE	180	0.0	0	0	180.00

Subtotal (before GST)	$ 4,745.70
GST (9%)	$ 427.11
TOTAL (GST inclusive)	**$ 5,172.81**

TERMS AND CONDITIONS

Quotation covers labour, parts and refinishing only; excludes paint materials consumed on a per-panel basis beyond the lines above. Any additional damage discovered on disassembly requires a supplementary quotation before work proceeds. This quotation does not constitute an instruction to repair. All prices in SGD, GST inclusive where stated.

AUTHORISED SIGNATORY / DATE