REPAIR QUOTATION

Bedok Motorworks Pte Ltd

WORKSHOP	Bedok Motorworks Pte Ltd	**UEN**	200801155W
DATE OF QUOTATION	13/07/2026	**VALID UNTIL**	31/12/2026
VEHICLE REGISTRATION NO.	PMN6118D	**CHASSIS NO.**	J3A3SC1CJ5E044771
MAKE / MODEL	Mitsubishi Lancer	**ENGINE CAPACITY (CC)**	1598
CLAIM REFERENCE	CLM-2026-CASE861		

WORKSHOP ADDRESS

31 Bedok North Street 4, Singapore 469847

PART C ITEMISED QUOTATION

Part No.	Description	Cat.	Parts	Hrs	Labour	Paint	Amount
P-5121	Front Bumper - replacement panel, primed and fitted	PANEL_REPLACE	1,958	3.5	520	702	3,179.25
P-2092	Front Left Wing - replacement panel, primed and fitted	PANEL_REPLACE	1,323	3.5	520	608	2,450.25
P-0001	Workshop consumables, panel adhesive, fasteners, solvent	CONSUMABLE	180	0.0	0	0	180.00

Subtotal (before GST)	$ 5,809.50
GST (9%)	$ 522.86
TOTAL (GST inclusive)	**$ 6,332.36**

TERMS AND CONDITIONS

Quotation covers labour, parts and refinishing only; excludes paint materials consumed on a per-panel basis beyond the lines above. Any additional damage discovered on disassembly requires a supplementary quotation before work proceeds. This quotation does not constitute an instruction to repair. All prices in SGD, GST inclusive where stated.

AUTHORISED SIGNATORY / DATE