REPAIR QUOTATION

Premium Auto Gallery Pte Ltd

WORKSHOP	Premium Auto Gallery Pte Ltd	**UEN**	201344871F
DATE OF QUOTATION	28/08/2026	**VALID UNTIL**	31/12/2026
VEHICLE REGISTRATION NO.	RYT4380E	**CHASSIS NO.**	WVWZZZ1KZAW000712
MAKE / MODEL	Volkswagen Golf	**ENGINE CAPACITY (CC)**	1395
CLAIM REFERENCE	CLM-2026-CASE947		

WORKSHOP ADDRESS

2 jalan Bukit Merah, Singapore 150126

PART C ITEMISED QUOTATION

Part No.	Description	Cat.	Parts	Hrs	Labour	Paint	Amount
P-4471	Front Left Wing - OEM assembly (front left fender, primed)	PANEL_REPLACE	2,180	4.5	495	980	3,655.00
P-9012	Front Parking Sensor Module (replaced as standard on wing assembly)	SENSOR	1,240	0.8	88	0	1,328.00
P-5580	Front Radar / ADAS Camera Calibration (required after bumper work)	CALIBRATION	640	1.5	165	0	805.00
P-7734	Three-stage refinish with colour blend into bonnet and headlamp	PAINT_BLENDING	0	6.0	660	1,450	2,110.00
P-8801	Diamond-coat underbody and sill protection (protection package)	ACCESSORY	2,100	1.0	110	0	2,210.00
P-0001	Workshop consumables, panel adhesive, fasteners, solvent	CONSUMABLE	180	0.0	0	0	180.00

Subtotal (before GST)	$ 10,288.00
GST (9%)	$ 925.92
TOTAL (GST inclusive)	**$ 11,213.92**

TERMS AND CONDITIONS

Quotation covers labour, parts and refinishing only; excludes paint materials consumed on a per-panel basis beyond the lines above. Any additional damage discovered on disassembly requires a supplementary quotation before work proceeds. This quotation does not constitute an instruction to repair. All prices in SGD, GST inclusive where stated.

AUTHORISED SIGNATORY / DATE