

Cat 337 HX Hydraulic Excavator - Product Spec Sheet

DEMO DOCUMENT - fictional product and values created for the Cat Track hackathon. Not an official Caterpillar specification.

Overview

The Cat 337 HX is a new 37-tonne hydraulic excavator that replaces the Cat 336 in quarry and highway work. It carries over the 336 operator station and adds a redesigned boom-foot hose route and a dust-rated cooling package, both developed from field reports of hose chafing and overheating.

Engine and power

Engine power: 232 kW

Engine model: C9.3B

Operating weight: 37900 kg

Fuel tank capacity: 600 L

DEF tank capacity: 41 L

Hydraulic system

Main system maximum pressure: 35 MPa

Maximum pump flow: 560 L/min

Swing speed: 9.6 rpm

Boom hoses run inside a steel guard channel at the boom foot, clear of the frame bracket. The guard replaces the abrasion sleeve and P-clamp used as a field fix on the Cat 336.

Cooling system

Side-by-side cooling package with a reversing fan that purges dust from the radiator and oil cooler cores every 30 minutes.

Maximum ambient temperature rating: 52 C

Service intervals

Engine oil and filter: replace every 500 hours.

Hydraulic oil filter: replace every 1000 hours.

Radiator and oil cooler cores: inspect every 250 hours, and every 100 hours at dusty sites.

Boom-foot hose guard: inspect for wear every 250 hours.

Air filter primary element: replace every 500 hours, or when the restriction indicator shows.

Fault codes

E3301 Boom hose pressure drop detected - hydraulic hose at boom foot. Stop the machine and inspect the hose guard.

E3415 Reversing fan cycle missed - cooling system. Check the fan drive and clean the cores.

CID 110 FMI 15 Engine coolant temperature high - cooling system.

Safety

Operators must not keep working with an active hydraulic leak.

Do not open the radiator cap while the engine is hot.

Keep the exclusion zone clear of ground crew when swinging; the 337 HX has a 360 degree camera system and a backup alarm that must be working before each shift.