

FME 500 mechanism: links, joints, and actuators

The fifth revolute joint is passive; cylinders C1--C4 are the learned actuator coordinates.

(a) CAD-derived topology



(b) coordinate chain



blue: actuated joint purple dashed: passive joint orange: cylinder