
(a) contact holds until authority is nearly gone
ground contact
1.0
0.9
0.8
0.7
0.6
gate 0.70
holds to $\alpha = 0.01$
0
mean over meshes
worst mesh
10^{-2}
10^{-1}
10^{0}
actuator authority α (fraction of nominal)


(b) and lateral error does not report it
lateral error (mm)
160
140
120
100
80
60
40
20
0
deviation metrics do not degrade:
a starved arm is stiller,
so contact is the metric that
reports the failure
10^{-2}
10^{-1}
10^{0}
actuator authority α (fraction of nominal)