
(a) what the effort buys
RMS valve command
0.9
0.8
0.7
0.6
0.5
IF (PPO-ID-FD)
lower is better
R (PPO-ROM)
0
50
100
150
mean absolute lateral error (mm)
(b) command reversals
R
IF
40.0
10.6
0
10
20
30
40
command reversals per second