
one control step: 17 ms
R (PPO-ROM)
IF (PPO-ID-FD)
command → pressure
450
167
pressure → cyl. velocity
0
167
command → cyl. velocity
283
283
cyl. velocity → joint velocity
17
17
static-linkage control
0
100
200
300
400
500
cross-correlation lag (ms)