
command → pressure
450
167
158
pressure → cyl. velocity
0
167
58
command → cyl. velocity
283
283
133
cyl. velocity → joint velocity
17
17
17
control: a static linkage. so this row must read zero
PPO-ROM
PPO-ID-FD
PPO-(AAM)-ID-FD
0
100
200
300
400
500
cross-correlation lag (ms)