

To Fatar Kbd MM or FFC connectors

Default: Diodes A on Tx, K on MKx/BRx

PL1

LEFT 32 KEYS

PL2

RIGHT 29 KEYS

PL8

KEYB J5

Matrix Polarity
Default: JP8

JP8

JP7

JP6

JP5

C12

4μF

PL6

FROM LWR OUT

R2

100R

R13

2k2

DVcc

DGnd

PL5

SCAN OUT

R4a R4b

100R 100R

R4c R4d R3

100R 100R 100R

47p

47p