

ISOTHERM ENGINEERING LTD.

95 Mural Street, Suite 600, Richmond Hill, ON, L4B 3G2
Ph 905-822-2430 • e-mail: info@isothermengineering.com

Project: Seneca Health & Wellness Reference: COM-2024-001	Cx Site Note #1	Date: 2026-06-22 By: Tony Faeghi
--	------------------------	---

Distribution

Name	Company	ABRV	Email
Uganda Tive	Seneca	Sen	ugandative@test.ca

Tony Faeghi made the following site review observations on June 22, 2026:

Site Progress Observations

Test test test

Required Documentations

Documents	Status	Issues Log Item #
TAB Report	OUTSTANDING	—
Equipment Shop Drawings	RECEIVED	—
Pipe Flushing Report	N/A	—

Observed Issues & Progress — Site Notes #1: 2026-06-22

#	Issue Details	Action
1	BAS 2026-06-21 BAS controller AHU-1 is not responding to setpoint changes. Controller appears to be in manual mode. Requires investigation by BAS vendor.	AME
2	INFO 2026-06-20 Test entry for informational note.	Sen
3	Controls/BAS 2026-06-21 Test entry two — additional observation recorded on follow-up visit. 2026-06-21 Follow-up note added. SoftwareAudit.org	AME
4 CLOSED	Geothermal 2026-06-21 Geothermal loop pressure reading below spec — flagged for review. 2026-06-21 Contractor adjusted loop pressure; verified within range. Closed.	AME