
US map of Power Plants and AQS monitors
Large coal power plant
Coal power plant
AQS monitor


avgPM_summer_decomposed75
Large coal power plant
Coal power plant
AQS monitor


Northeast − summer 2005
Large coal power plant
Coal power plant
AQS monitor
lag 0 edge
lag 1 edge
lag 2 edge
lag 3 edge


IndustrialMidwest − summer 2005
Large coal power plant
Coal power plant
AQS monitor
lag 0 edge
lag 1 edge
lag 2 edge
lag 3 edge


Southeast − summer 2005
Large coal power plant
Coal power plant
AQS monitor
lag 0 edge
lag 1 edge
lag 2 edge
lag 3 edge


Edge Probability by Lag
0.00
0.02
0.04
0.06
0.08
0.10
0.12
0.14
0
1
2
3


Edge Probability by Direction from Power Plant to Receptor (Northeast Power Plants)
0.00
0.02
0.04
0.06
0.08
0.10
0.12
N
NE
E
SE
S
SW
W
NW


Edge Probability by Direction from Power Plant to Receptor (IndustrialMidwest Power Plants)
0.00
0.02
0.04
0.06
0.08
0.10
0.12
N
NE
E
SE
S
SW
W
NW


Edge Probability by Direction from Power Plant to Receptor (Southeast Power Plants)
0.00
0.01
0.02
0.03
0.04
N
NE
E
SE
S
SW
W
NW


summer 2005 Lag 0 edges
Large coal power plant
Coal power plant
AQS monitor
lag 0 edge
lag 1 edge
lag 2 edge
lag 3 edge


summer 2005 Lag 1 edges
Large coal power plant
Coal power plant
AQS monitor
lag 0 edge
lag 1 edge
lag 2 edge
lag 3 edge


summer 2005 Lag 2 edges
Large coal power plant
Coal power plant
AQS monitor
lag 0 edge
lag 1 edge
lag 2 edge
lag 3 edge


summer 2005 Lag 3 edges
Large coal power plant
Coal power plant
AQS monitor
lag 0 edge
lag 1 edge
lag 2 edge
lag 3 edge

sum of gams.coeff summer 2005



avgPM_decomposed75 summer 2005



sum of gams.coeff summer 2005



avgPM_decomposed75 summer 2005



num_edges summer 2005



num_edges summer 2005




Northeast correlation = NA
Ranked Exposure avgPM
50
100
150
200
80
100
120
140
160
Ranked Exposure gams.coeff


Southeast correlation = NA
Ranked Exposure avgPM
50
100
150
200
250
80
100
120
140
160
180
Ranked Exposure gams.coeff


IndustrialMidwest correlation = NA
Ranked Exposure avgPM
250
200
150
100
50
80
100
120
140
160
Ranked Exposure gams.coeff


Northeast correlation = NA
Ranked Exposure inmapPM
0
50
100
150
200
80
100
120
140
160
Ranked Exposure gams.coeff


Southeast correlation = NA
Ranked Exposure inmapPM
0
50
100
150
200
250
80
100
120
140
160
180
Ranked Exposure gams.coeff


IndustrialMidwest correlation = NA
Ranked Exposure inmapPM
0
50
100
150
200
250
80
100
120
140
160
Ranked Exposure gams.coeff