

Holes Between Columns Not Connected
Holes Along Rows are NOT Connected
Holes Along Columns Are Connected
These Holes Are All Connected Together
you rolling with this but let's go back and let's look at this I

sketch.ino ● diagram.json ● Library Manager


```ino
void setup() {
  // put your setup code here, to run once:
  pinMode(13,OUTPUT);
}

void loop() {
  // put your main code here, to run repeatedly:
  digitalWrite(13,HIGH);
  delay(500);
  digitalWrite(13,LOW);
  delay(500);
}

```

Simulation

00:05.496 72%



sketch.ino ● diagram.json ● Library Manager

```
1  void setup() {
2    // put your setup code here, to run once:
3    pinMode(13,OUTPUT);
4  }
5
6  void loop() {
7    // put your main code here, to run repeatedly:
8    digitalWrite(13,HIGH);
9    delay(500);
10   digitalWrite(13,LOW);
11   delay(500);
12 }
13
```

Simulation

