

WindOps Copilot - Turbine Report

Turbine ID: WTG-001 | Correlation ID: corr-fc5e01df520a
Report Generated: 2026-06-26T12:50:32.747688

TURBINE HEALTH STATUS

60.0% Health

Live Sensor Telemetry

Sensor Parameter	Value	Unit
Wind Speed	28.50	m/s
Rotor Speed	4.20	RPM
Blade Temperature	18.00	°C
Generator Temperature	32.00	°C
Vibration	0.14	mm/s
Power Output	0.00	MW
Operational Status	curtailed	

Active Fault Alerts

Parameter	Value	Threshold	Severity
Wind Speed	28.50	25.00	CRITICAL

Diagnostic Root Cause Analysis

Diagnosed Cause:	Extreme Wind / Storm Ingress
Confidence Level:	95.0%
Technical Analysis:	Wind speeds are currently at 28.5 m/s, exceeding the structural safety threshold of 25.0 m/s. High aerodynamic loads present severe risks of turbine overspeed and rotor structural damage.

Operational Action Recommendations

Recommended Action	Description	Risk	Production Loss	Confidence
Emergency Controlled Shutdown	Trigger pitch feathers and rotor brake immediately due to extreme storm conditions (>25 m/s). Protect structural integrity of the asset.	LOW	severe	100%

De-rate / Curtail Power Output	Reduce generator speed. (NOT RECOMMENDED: safety thresholds are violated, structural damage is likely if kept spinning).	HIGH	moderate	10%
---	--	-------------	----------	-----

Note: This report is generated by an autonomous multi-agent system. final actions must be reviewed and authorized by a human operator.