

**A. Clean wood at tau=0.25**

A1 crop tau=0.25




P4+A4 combined tau=0.25




**B. Missed knots vs retained recall**

Baseline tau=0.60



P4+A4 combined tau=0.35




**C. Correct detection at tau=0.35**

P4+A4 combined tau=0.35




**D. Clean-wood confidence at tau=0.10**

A1 crop tau=0.10



A2 color jitter tau=0.10



P2 illumination tau=0.10

