ECGR 4101/5101 LECTURE 20 Embedded Ap of the day: Power Botix MSP 430 F2272 Battery Input Module FT232 RL PBBI 001 4 controller Problem: Moder Start-Inrush cument may cause incontroller to dip below Vcc Solution

ECGR 4101/5101 LECTURE 20 Write the Validate-worey-and_item function @ Assumptions: Globals: money_count button value Hem-cost[i] Validale_money_and_Hem (Void) & if money_count >= item_cost[button_value] state = vend_and_retwn State = money state display price on screen botton value = nul

ECGR 4101/5101 waskable? No/Yes? No rimer 2chru button press 150 State changed from money state to validate money and Hem return money 1572 Ortan-Pless-15R Press return button State change from state woney state money state