

VIEW A-A



ISOMETRIC VIEW

METRIC

NOTES: (UNLESS OTHERWISE SPECIFIED)

1. MAXIMUM FASTENER ENGAGEMENT: 17±0.5 mm
   MINIMUM THREAD ENGAGEMENT: 10 THREADS.

2. FREE MACHINING BRASS
   JIS H3250 C3604, UNS 38000
   MIN HARDNESS: VICKERS 125
   ROCKWELL B 69

WORLDWIDE DRAWING

ALL PARTS MUST BE INTERCHANGEABLE, SEE EN0230015
ARROW METHOD OF VIEW PROJECTION PER ISO 128-30 & ISO 5456-2

MATERIAL	RELEASE NO.	201704192	TITLE
SEE NOTE 2	DATE	SEPT 15, 2017	INSERT, M8 X 1.25 X 28
	EXP DATE		
	DWN	H. RAHN	NUMBER
REFERENCE	DATE	AUG 08, 2017	P636128
	CHK		
	DATE		SCALE - SHEET 1 OF 1 REVISION
PREVIOUS DRAWING NO.	APVD	D. TWEETON	C/C PROE/CADD 3
DO NOT SCALE / TOLERANCES UNLESS OTHERWISE SPECIFIED: 1 PL ±, 2 PL ±, ANGLES ±	DATE	AUG 08, 2017	SECTIONAL SIZE X OUTLINE SIZE NO
	[redacted]		DESIGN CONTROL A001 DWG LOCATION A100 VERSION W
			L B