

Pump P-204 Preventive Maintenance Procedure

Equipment Tag: P-204 (Centrifugal Pump)

Location: Process Area 3, Unit 200

Standard Reference: OISD-STD-105

Prepared by: Rajesh Kumar, Maintenance Engineer

Approved Date: 2026-01-10

1. SAFETY PRECAUTIONS

- Obtain lockout-tagout (LOTO) permit before starting work.
- Wear PPE: safety glasses, gloves, steel-toe boots.
- Verify pump is isolated from process and depressurized.

2. PROCEDURE

Step 1: Isolate electrical power at MCC and apply LOTO.

Step 2: Inspect mechanical seal for leaks or wear.

Step 3: Check vibration readings against baseline (max 4.5 mm/s RMS).

Step 4: Lubricate bearings per OEM schedule.

Step 5: Verify shaft alignment within 0.05mm tolerance.

Step 6: Remove LOTO and restart pump; confirm normal operation.

3. NEXT SCHEDULED MAINTENANCE

Next inspection due: 2026-07-10

Reference work order: WO-2039