

Standards Mapping

PEDO *Checklist for Accessibility Audit* vs *Accessibility Code of Pakistan 2006*

Appendix B to the Product Requirements Document — Phase 1 deliverable

September 1, 2026

Status	Draft. Not reviewed by a qualified access consultant. No value here may be cited in an issued report until it is.
Sources	PEDO, <i>Checklist for Accessibility Audit</i> (71 pp.); <i>Accessibility Code of Pakistan 2006</i> , Chapters 3–8
Not yet consulted	<i>Design Manual and Guidelines for Accessibility 2006</i> — scanned, no text layer. Rows marked GAP: CODE are the ones it is most likely to resolve.
Machine-readable	standards_mapping.csv, requirements_seed.json

1 Headline

114 requirements were compared. **Twelve agree.**

Verdict	Count	Share
MATCH	12	11%
CODE STRICTER	21	18%
CHECKLIST STRICTER	5	4%
CONFLICT	24	21%
GAP: CHECKLIST	43	38%
GAP: CODE	9	8%
Total	114	100%

1.1 What this means

- The checklist is substantially an adaptation of United States ADA guidance. That is not a criticism of its authors, but it has three consequences the tool must handle.
- 38% of Code requirements are absent from the checklist.** An audit run against the checklist alone silently omits illumination levels, emergency egress computation, areas of refuge, signage character height, ramp rise and run limits, motorcycle parking scoping, and the Muslim shower provision, among others. These are not edge cases.
 - 21% conflict outright.** In several the ranges barely overlap, so the same building passes one document and fails the other. `wc.centreline` is the worst: 16–18 in by the checklist, 18–21 in by the Code.
 - Only 11% match.** Adopting the Code is not a matter of adjusting a few numbers. It changes most thresholds in the instrument.

1.2 Resolution rule applied

Unless a row says otherwise, the applied value follows the Code, because it is the Pakistani instrument and the checklist's stated purpose is to establish minimum standards locally. Three exceptions are marked in the table:

- Where the Code is silent (GAP: CODE), the checklist value is retained and flagged as unsourced pending the Design Manual.
- Where the checklist is materially stricter and the Code's floor is low enough to be unsafe (`grab.bar.length`, `door.threshold`), the checklist value is retained and the divergence must be disclosed in the report.
- Where the Code phrases a provision as *should* or *where possible*, it is recorded as advisory and must not generate a failure.

1.3 Legal status — read before issuing anything

As of 2026, Khyber Pakhtunkhwa has no provincial statute binding this Code. KP is the only province not to have repealed the Disabled Persons (Employment and Rehabilitation) Ordinance 1981; the KP Empowerment of Persons with Disabilities Bill remains unadopted. Punjab's 2022 Act and Sindh's 2018 Act both bind the Code expressly; KP has no equivalent.

Consequently every finding generated from this table is a **departure from a published minimum standard**, not a legal violation. Recommendation templates must be worded accordingly.

1.4 Highest-priority resolutions

1. `wc.centreline` — ranges do not meaningfully overlap.
2. `parking.count.car` — entirely different scoping method; changes the finding on nearly every site with parking.
3. `parking.marking` — the two documents directly contradict each other on whether ground marking is required.
4. `assembly.wheelchair.count` — the checklist contradicts *itself*; its note says 5% and its table yields roughly 2.7–8%.
5. `route.width.interior` and `route.width.exterior` — 36 in vs 48 in affects almost every site.
6. `illumination.general` — adopting it requires a light meter in the kit.
7. `egress.count` — replaces four yes/no questions with a computation.

2 Mapping Table

Requirement key	Checklist	Code 2006	Verdict	Applied value / note
Accessible route				
<code>route.width.exterior</code>	3.2 — 36 in min	5.2.1(iii) — 48 in min	CODE STRICTER	48 in EXTERIOR Code also requires handrail protection where level drop from adjoining ground exceeds 18 in.
<code>route.width.interior</code>	9.3 — 36 in min, may narrow to 32 in for max 24 in	6.2.1(ii) — 48 in min except at doors	CODE STRICTER	48 in INTERIOR Checklist narrowing allowance has no Code equivalent.
<code>route.passing.space</code>	9.3 — narrow portions 48 in apart	6.2.1(iii) — if width < 60 in, provide 60 x 60 in passing spaces at intervals not exceeding 100 ft	CONFLICT	Code INTERIOR Different mechanism entirely. Corridor intersection counts as passing space.
<code>route.headroom</code>	11.78 — 6 ft 6 in (78 in)	6.2.1(v) — 80 in min	CODE STRICTER	80 in Checklist value appears under landscape planting; Code sets it for the whole accessible route.
<code>route.level.gradient</code>	3.3, 9.4 — running slope not steeper than 1:20	5.2.1(ii) — gradient less than 1:20 is level access	MATCH	1:20
<code>route.surface</code>	3.1, 9.2 — stable, firm, slip-resistant	5.2.5(i), 6.2.2(iii) — firm, slip-resistant, reasonably smooth, especially under wet conditions	CODE STRICTER	Code Code names wet conditions explicitly.
<code>route.tactile</code>	1.3 — tactile blocks in sidewalk and crossing	5.2.5(ii) — detectable tactile surface across full width at each level change and at head and foot of ramps and steps	CODE STRICTER	Code Code is more specific about placement.
<code>route.egress.link</code>	not asked	6.2.1(vi) — a sole accessible route must also serve as means of emergency egress or connect to an area of refuge	GAP: CHECKLIST	Code New item required.
Walkways				
<code>walkway.width</code>	3.2 — 36 in	5.2.7(i) — 48 in min; 36 in clear at identified obstructions	CODE STRICTER	48 in / 36 in at obstruction EXTERIOR
<code>walkway.gradient</code>	not asked	5.2.7(ii) — should not exceed 1:12	GAP: CHECKLIST	1:12 EXTERIOR
<code>walkway.gratings</code>	not asked	5.2.7(iv) — no parallel bars; apertures at right angles to travel, not larger than 1 in wide	GAP: CHECKLIST	1 in EXTERIOR New item required.
Pedestrian crossings				
<code>crossing.curbramp</code>	4.1, 11.49, 11.52 — curb ramp where route crosses curb; level differences over 19 mm	5.2.8(i), 5.2.7(iii) — all marked crossings shall have curb ramps and detectable floor paving	CODE STRICTER	Code EXTERIOR Checklist 11.49 uses 19 mm, the only metric value in an otherwise imperial document; no Code basis found.
<code>crossing.signals</code>	11.48, 11.51 — audible and flashing crossing signals	5.2.8(iii) — auditory signals and manually operated traffic lights where possible in high pedestrian traffic areas	CONFLICT	Code EXTERIOR Checklist states it as a requirement; Code phrases it as 'where possible'. Downgrade severity.

Requirement key	Checklist	Code 2006	Verdict	Applied value / note
crossing.width	11.50 — at least 10 ft wide, 4 in white lines	not specified	GAP: CODE	checklist, flagged no Code basis No Code basis. Check Design Manual before citing.
Ramps				
ramp.slope.new	6.3, 9.16 — 1:12 max; 1:8 for rise ≤ 3 in, 1:10 for rise ≤ 6 in where space limited	5.2.3(i) — should not exceed 1:20; shall not exceed 1:12 for new construction	CONFLICT	1:12 NEW Code gives no space-limitation exception for new build. Checklist exceptions are ADA-derived.
ramp.slope.existing	not distinguished	5.2.3(ii) — up to 1:8 permitted for existing development ONLY where an alternative stepped approach is also provided	GAP: CHECKLIST	1:8 conditional EXISTING Requires new-vs-existing site attribute and a conditional threshold.
ramp.crossslope	8.2 — 1:48 (door manoeuvring)	5.2.3(iii) — 1:50 max	CONFLICT	1:50 Minor numeric difference; adopt Code.
ramp.width.exterior	6.1 — 36 in min	5.2.3(iv) — 48 in min	CODE STRICTER	48 in EXTERIOR
ramp.width.interior	9.14 — 36 in min	6.2.3(v) — 36 in min with passing space at landings	MATCH	36 in INTERIOR Exterior and interior differ in the Code; the checklist uses one value for both.
ramp.rise.max	not asked	5.2.3(v) — max rise between two landings 30 in	GAP: CHECKLIST	30 in New item required.
ramp.run.max	not asked	6.2.3(iv) — single run shall not exceed 48 ft	GAP: CHECKLIST	48 ft INTERIOR New item required.
ramp.landing	6.4, 6.5, 9.17, 9.18 — 60 in long, ramp width; 60 x 60 in at direction change	6.2.3(v) — passing space provided at landings (undimensioned)	GAP: CODE	checklist, flagged Code does not dimension landings. Check Design Manual.
ramp.handrail.trigger	6.6, 9.19 — handrails both sides if rise > 6 in	7.7.1 — handrails required unless gradient is less than 1:20	CONFLICT	Code Different trigger: rise-based vs gradient-based.
ramp.balustrade	not asked	7.7.2 — balustrade required where drop to the side exceeds 18 in	GAP: CHECKLIST	18 in New item required.
Stairs				
stair.riser.exterior	5.1 — not more than 6.5 in	5.2.4(ii) — not more than 6 in	CODE STRICTER	6 in EXTERIOR
stair.riser.interior	9.6 — not more than 6.5 in	6.2.3(iii) — max riser 7 in	CHECKLIST STRICTER	6.5 in, flagged INTERIOR Three different values across the two documents. Resolve with consultant.
stair.tread	5.1, 9.6 — not less than 11 in	5.2.4(ii), 6.2.3(iii) — not less than 11 in	MATCH	11 in Code 6.2.3(iii) says 'head width', read as tread.

Requirement key	Checklist	Code 2006	Verdict	Applied value / note
stair.width.exterior	5.2 — asked, no threshold given	5.2.4(i) — not less than 36 in	GAP: CHECKLIST	36 in EXTERIOR Checklist records the measurement but sets no pass criterion.
stair.width.interior	9.7 — asked, no threshold given	6.2.3(ii) — min 42 in clear between handrails (low-rise buildings)	GAP: CHECKLIST	42 in INTERIOR
stair.single.step	not asked	5.2.4(iii) — single steps should be avoided	GAP: CHECKLIST	advisory EXTERIOR 'Should' - preferred standard, not mandatory.
Handrails				
handrail.height.exterior	5.2 — 34 to 38 in	5.2.6(iii) — not less than 30 in, not more than 42 in	CONFLICT	30 to 42 in EXTERIOR Checklist range sits inside Code range; a 32 in rail passes Code, fails checklist.
handrail.height.general	5.7, 9.9, 9.20 — 34 to 38 in	7.7.3 — not less than 30 in, not more than 48 in	CONFLICT	30 to 48 in Code is markedly wider. Adopt Code; note the divergence in the report.
handrail.diameter	5.5, 6.8, 9.10, 9.21 — circular 1.25 to 2 in dia	5.2.6(ii), 7.7.4 — circular or oval, max 2 in dia at grip; no lower bound	CONFLICT	max 2 in Code sets no minimum. Retain checklist minimum as advisory.
handrail.noncircular	5.6, 6.9, 9.11, 9.22 — perimeter 4 to 6.25 in	7.7.4 — circular or oval only	CONFLICT	Code Code effectively disallows non-circular profiles; checklist dimensions them.
handrail.extension	5.3, 9.8 — extend 12 in beyond top and bottom	5.2.6(ii), 6.2.3(vii), 7.7.4 — extend min 12 in beyond step or ramp, horizontally, at each end	MATCH	12 in
handrail.wall.clearance	2.27, 12.28 — 1.5 in space to wall (grab bars)	7.7.4 — fixed min 1.5 in from wall surface	MATCH	1.5 in
handrail.parallel.spacing	not asked	6.2.3(vi), 7.7.5 — max 72 in between parallel handrails	GAP: CHECKLIST	72 in New item required.
handrail.both.sides	5.3, 9.8 — continuous rails both sides	5.2.4(iv), 6.2.3(vi) — outdoor: at least one side. Accessible stair/ramp: both sides	CONFLICT	both sides interior, one side min exterior Code is weaker outdoors.
handrail.ends	not asked	7.7.4 — ends shall be rounded and not become hazardous as protruding objects	GAP: CHECKLIST	Code
Parking				
parking.count.car	2.1 — 1-25:1, 26-50:2, 51-75:3, 76-100:4	5.2.9(ii),(iii) — under 20 spaces: none required. 20-50: at least 1. Over 50: min 2 percent	CONFLICT	Code Materially different. At 100 spaces: checklist 4, Code 2. Below 20 spaces the Code requires none.
parking.width.car	2.5 — 8 ft space + 5 ft aisle	5.2.10(i) — not less than 12 ft total, inclusive of a 48 in access aisle	CONFLICT	12 ft incl. 48 in aisle Checklist totals 13 ft; Code totals 12 ft with a narrower aisle.
parking.aisle.shared	2.5 — two spaces may share an aisle	5.2.10(ii) — a 48 in aisle may be shared between two adjacent spaces	MATCH	shared permitted
parking.van	2.3, 2.4 — 1 van space per 6; 11 ft + 5 ft aisle, or 8 ft + 8 ft	not specified	GAP: CODE	drop or mark advisory no Code basis Van-accessible space is an ADA concept with no Code equivalent.

Requirement key	Checklist	Code 2006	Verdict	Applied value / note
parking.motorcycle	2.2 — scooter space 4 x 5 ft, 3 ft gap	5.2.9(iv),(v), 5.2.10(iii) — 50+ combined m/cycle and cycle spaces: 1 reserved. Over 50: min 4 percent. Width not less than 6 ft	CONFLICT	Code Code has scoping and a wider space; checklist has different dimensions and no scoping.
parking.headroom	not asked	5.2.10(iv) — indoor accessible parking min height clearance 8 ft	GAP: CHECKLIST	8 ft INTERIOR New item required.
parking.location	2.6 — access aisles adjoin an accessible route	5.2.9(vi) — reserved spaces located in clear view of and nearest to the accessible entrance	CODE STRICTER	Code Code adds proximity and visibility, not just connectivity.
parking.multistorey	not asked	5.2.9(i) — at least one floor of a multi-storey indoor parking facility served by accessible lift or ramp	GAP: CHECKLIST	Code INTERIOR
parking.marking	2.7 — sign with ISA, bottom min 60 in above ground; ground marking not required	5.2.10(v) — clearly identified on the ground surface with internationally accepted markings	CONFLICT	Code Direct contradiction: checklist says ground marking not required, Code requires it.
Doors				
door.width.entrance	8.1 — 32 in clear at 90 degrees	5.2.2(ii), 6.2.2(i) — not less than 33 in clear, and 80 in high, opening in direction of travel	CODE STRICTER	33 in Code also sets door height, which the checklist omits.
door.width.internal	not asked separately	7.6.6 — 33 in when approached at an angle; 30 in when approached straight on	GAP: CHECKLIST	33 in / 30 in by approach INTERIOR Approach-dependent threshold; needs a conditional.
door.width.toilet	12.6 — 32 in clear	7.3.9 — at least 30 in clear	CHECKLIST STRICTER	32 in, flagged
door.threshold	8.3, 12.8 — 0.25 in max if vertical	6.2.2(iii) — level change at threshold shall not exceed 0.75 in	CHECKLIST STRICTER	0.75 in Threefold difference. Adopt Code as the pass threshold; note checklist value as preferred.
door.handle.height	8.4, 12.10 — 34 to 48 in	7.6.7 — not less than 38 in, not more than 42 in; lever-type handles	CONFLICT	38 to 42 in Code is much narrower and mandates lever handles explicitly.
door.handle.clearance	8.2, 12.7 — 18 in beyond latch side plus 60 in clear depth	7.6.2 — unobstructed space min 12 in adjacent to door handle on leading face	CONFLICT	Code, checklist advisory Different measurement basis.
door.force	8.6, 12.11 — 5 lbf max	not specified	GAP: CODE	checklist, flagged no Code basis No Code basis. Requires a pressure gauge; consider dropping from MVP.
door.swing.toilet	12.34 — compartment area beyond swing	7.6.3 — toilet doors to accessible compartments shall invariably open out	CODE STRICTER	Code Code mandates outward swing; checklist only dimensions the inward case.
door.kickplate	not asked	7.6.8 — kick plates not less than 10 in high	GAP: CHECKLIST	10 in New item required.
door.revolving	not asked	7.6.5 — revolving doors shall not be considered accessible; automatic swing doors shall not open against direction of travel	GAP: CHECKLIST	Code New item required.
door.glass	not asked	7.6.9 — frameless glass doors avoided unless prominently marked	GAP: CHECKLIST	Code

Requirement key	Checklist	Code 2006	Verdict	Applied value / note
Space allowance				
space.wheelchair.stationary	11.6, 12.19 — 30 x 48 in clear floor space	7.2.1 — 36 x 48 in for stationary wheelchair; 48 x 48 in for both forward and side approach	CODE STRICTER	36 x 48 in Checklist uses the ADA 30 in figure throughout.
space.turning	11.8, 11.15, 11.17, 12.16 — 60 in circle or T-shape in 60 in square	7.2.1 — 60 in diameter circle	MATCH	60 in circle Code does not mention the T-shaped alternative.
space.forward.reach	10.1 — operable parts no higher than 48 in	7.2.2 — forward reach 16 in min to 48 in max; over an obstruction max 20 in; side reach 10 to 52 in	CODE STRICTER	Code Code sets a lower bound the checklist omits.
space.cane.zone	9.5 — protrusions max 4 in; leading edge 27 in or lower, or 80 in or higher	7.2.2 — white cane zone extends 48 in across and 28 in in height	CONFLICT	Code 28 in 27 in vs 28 in detection height.
Sanitary facilities				
toilet.provision	12.1 — at least one accessible toilet, per sex or unisex	7.3.1 — at every floor where toilets are provided, at least one accessible toilet for male and female	CODE STRICTER	Code Code requires this per floor, not per building.
toilet.clear.space	12.16 — 60 in turning circle	7.3.2 — at least 60 in wide clear space in both directions; smaller toilets shall have door opening outside	MATCH	60 in
wc.seat.height	12.26 — 17 to 19 in to top of seat	7.3.4 — 18 to 20 in above floor level	CONFLICT	18 to 20 in Ranges overlap only between 18 and 19 in.
wc.centreline	12.24 — 16 to 18 in from side wall	7.3.4 — 18 to 21 in from centre line to adjoining wall	CONFLICT	18 to 21 in RANGES BARELY OVERLAP. A 17 in installation passes the checklist and fails the Code. Highest-priority resolution.
wc.type	12.23 — is the facility commode (yes/no)	7.3.4 — European type water closet; back support if un-coupled	CODE STRICTER	Code Code adds the back-support requirement.
wc.muslim.shower	not asked	7.3.5 — reachable Muslim shower shall be provided at the adjoining wall	GAP: CHECKLIST	Code Locally significant requirement entirely absent from the ADA-derived checklist.
grab.bar.length	12.27, 12.28 — 42 in side wall, 36 in rear wall	7.7.6 — not less than 24 in	CHECKLIST STRICTER	checklist, flagged Code sets a much lower floor. Retaining the checklist value is defensible but must be disclosed.
grab.bar.projection	12.27, 12.28 — 1.5 in space between wall and bar	7.7.6 — shall extend 2 in away from the wall	CONFLICT	2 in
grab.bar.diameter	not asked	7.7.6 — external diameter between 1 and 2 in; plastic covered preferred over chrome; slightly corrugated surface recommended	GAP: CHECKLIST	1 to 2 in New item required.
mirror.height	12.18 — bottom edge max 40 in	7.3.7 — bottom of mirror not more than 40 in above floor level	MATCH	40 in
toilet.controls.height	12.29 — flush control max 48 in	7.3.7 — all operable parts and controls of fixtures within 40 to 48 in above floor level	CODE STRICTER	40 to 48 in Code sets a lower bound.
basin.type	12.20, 12.21 — front max 34 in; 27 in knee clearance, 8 in deep	7.3.3 — wall mounted with lever handle controls; insulated and concealed hot water pipes	GAP: CODE	both Code specifies type and safety, checklist specifies geometry. Merge; neither supersedes the other.

Requirement key	Checklist	Code 2006	Verdict	Applied value / note
toilet.door.pullbar	not asked	7.3.9 — 24 in pull bar on inside; lockable inside, releasable from outside in emergency; spring or gravity closing hinges	GAP: CHECKLIST	Code New item required; the emergency-release provision is a safety requirement.
shower.area	not asked	7.3.6 — clear dimension 48 x 48 in; horizontal grab bar and folding waterproof shower seat preferred	GAP: CHECKLIST	48 x 48 in
Lifts				
lift.provision	9.23 — elevators or platform lifts to all public storeys	6.2.3(i) [second] — in all multi-storey buildings at least one accessible lift serving all accessible floors	MATCH	Code INTERIOR
lift.door.width	9.26, 9.27 — 32 in min (full size), 36 in (LULA variant)	7.8.1 — min clear width 30 in; sliding or outward opening	CHECKLIST STRICTER	32 in, flagged INTERIOR LULA is an ADA category with no Code equivalent.
lift.controls.height	9.28 — 15 to 42 in, or up to 48 in for parallel approach	7.8.1 — switches and controls not more than 48 in above floor level	MATCH	Code max 48 in INTERIOR Code sets no lower bound; retain 15 in as advisory.
lift.braille	9.29 — raised characters and Braille on car controls	7.8.1, 7.8.4 — talking and Braille signs in addition to regular signs	CODE STRICTER	Code INTERIOR Code requires audible announcement, not merely tactile marking.
lift.size	9.26 — 54 in deep x 36 in wide, 16 sq ft min	7.8.3 — size such that it accommodates at least one wheelchair user with an attendant (undimensioned)	GAP: CODE	checklist, flagged INTERIOR Code is qualitative. Check Design Manual for the dimension.
lift.floor	not asked	7.8.2 — cab floor slip-resistant; walls resistant to wheelchair damage	GAP: CHECKLIST	Code INTERIOR
lift.freight	not asked	7.8.6 — a freight elevator shall not be considered an accessible lift	GAP: CHECKLIST	Code INTERIOR Disqualifying condition; affects NA logic.
Controls				
controls.height	10.1 — operable parts no higher than 48 in	7.9.1 — recommended height 42 in above floor level	CONFLICT	max 48 in, 42 in preferred Code phrases 42 in as a recommendation, not a limit.
controls.pullknob	not asked	7.9.2 — pull knobs for ceiling switches not more than 40 in above floor	GAP: CHECKLIST	40 in
Signage				
signage.character.height	not asked	6.2.6(ii) — minimum character height 3 in for accessibility signage	GAP: CHECKLIST	3 in Significant gap. Checklist covers Braille placement but never character size.
signage.braille.height	Ch.1 — Braille and tactile between 900 and 1500 mm, ideal 1050 mm	5.2.12(ii) — directional and guidance signs supplemented with Braille where within reach	GAP: CODE	checklist, flagged Checklist Chapter 1 is the only metric section in the document; no Code basis for the figures.
signage.illuminated	not asked	5.2.12(i), 6.2.6(iii) — signs shall be illuminated internally or externally	GAP: CHECKLIST	Code New item required.
Illumination				

Requirement key	Checklist	Code 2006	Verdict	Applied value / note
illumination.general	15.4 asks 'adequate and without glare', unquantified	5.2.11, 6.2.3(ii),(iii) — min 5 foot-candle (55 lux) at all times; general illumination preferably 10 to 20 foot-candle (110 to 220 lux)	GAP: CHECKLIST	55 lux min Requires a light meter in the tool kit. Significant addition to the instrument.
illumination.backup	not asked	6.2.3(iv) — on power failure, illumination maintained by emergency supply for the duration the space is occupied	GAP: CHECKLIST	Code INTERIOR
Assembly seating				
assembly.wheelchair.count	11.40 — table 4-25:1, 26-50:2, 51-150:4, 151-300:5, with a note stating 5 percent	7.5.1 — 2 percent of seats reserved for wheelchair users	CONFLICT	2 percent Checklist is internally inconsistent: its note says 5 percent, its table yields roughly 2.7 to 8 percent.
assembly.paired	not asked	7.5.2 — designated wheelchair spaces should where possible be paired	GAP: CHECKLIST	advisory
assembly.clear.space	11.43, 11.44, 11.45 — 36 in wide; 48 in deep front/rear entry; 60 in side entry	7.5.5 — 36 in wide clear space in front of first row or behind last row	GAP: CODE	both Different aspects; merge rather than choose.
assembly.stage	11.39 — ramp to stage/podium if provided	7.5.7 — the stage or activity area shall be accessible	MATCH	Code
Seating				
seating.dining.count	11.3 — at least 5 percent, no fewer than one	not specified	GAP: CODE	checklist, flagged no Code basis No Code basis for dining seating percentage.
Counters				
counter.height	11.5, 11.36 — 28 to 34 in dining; max 36 in service counter	7.4.2 — counter tops 30 to 33 in high; depth not more than 21 in; clear knee space underneath	CONFLICT	30 to 33 in Code range is narrower and adds a depth limit.
shelving.height	11.29, 11.30, 11.38 — displays max 36 in; overhead shelves above 49 in; dispensers max 48 in	7.4.4 — shelves and storage between 12 and 48 in above floor level	CONFLICT	12 to 48 in Code sets a lower bound the checklist lacks.
hotwater.insulation	not asked	7.4.5, 7.3.3 — all exposed hot water pipes under sinks and counters shall be insulated and concealed	GAP: CHECKLIST	Code Safety requirement absent from the checklist.
Emergency egress				
egress.count	14.1, 14.2 — exits identifiable and accessible (qualitative)	8.2.2(ii) — one accessible egress per 5,000 sq ft gross floor area, or occupant load of 50, or 100 ft travel distance, whichever is most stringent	GAP: CHECKLIST	Code Major gap. Checklist has four qualitative questions where the Code has a computation.
egress.lift	14.3 — is the lift an evacuation lift	8.2.3(iii), 7.8.5 — fire-protected construction; operable on emergency power for at least 30 minutes; egress signage; illuminated	CODE STRICTER	Code Checklist asks yes/no; Code gives four testable criteria.
egress.illumination	not asked	8.2.4 — at least 1 foot-candle (11 lux) at floor level; on failure, emergency supply for 30 min at min 0.1 foot-candle (1 lux)	GAP: CHECKLIST	Code
egress.alarm	13.1 — alarms have flashing lights and audible signals	8.2.6 — auditory and visual signals covering the entire accessible space	CODE STRICTER	Code Code adds full coverage.
egress.refuge	not asked	8.3.1 — area of refuge required in all multi-storey buildings and low-rise with 5,000 sq ft accessible floor area; must hold two wheelchairs with attendants; communication to managerial station; tactile door handle warnings	GAP: CHECKLIST	Code Entire concept absent from the checklist. Multiple new items.

Requirement key	Checklist	Code 2006	Verdict	Applied value / note
<code>egress.plan</code>	14.4 — is safety drill performed (yes/no)	8.3.2 — written rescue assistance plan required; copy to on-site staff and to the government evacuation agency; drill at least once every year	CODE STRICTER	Code Checklist has no frequency and does not ask for the plan document.
<code>egress.hospital.ramp</code>	not asked	8.2.7 — in hospitals and buildings for persons requiring mobility assistance, an accessible ramp for egress should be considered	GAP: CHECKLIST	advisory Sector-gated to Health.
Scoping				
<code>scope.exemption.smallprivate</code>	not asked	3.2.4(iii), 4.3.3(xi)(b) — existing privately owned public-use buildings under 2,500 sq ft gross floor area are exempt	GAP: CHECKLIST	Code EXISTING Gating condition. Requires site ownership type, gross floor area and new/existing attributes.
<code>scope.government</code>	not asked	3.2.1 — all government-owned or government-occupied buildings covered irrespective of size, location or use	GAP: CHECKLIST	Code No exemption path for government buildings.
<code>scope.mandatory.vs.preferred</code>	items weighted equally	4.2.2 — mandatory requirements (total compliance new, achievable existing) vs preferred standards (voluntary)	GAP: CHECKLIST	Code Maps directly onto item severity weighting. Chapter 4.3 assigns mandatory/preferred per building type.
<code>scope.residential.units</code>	not asked	4.3.3(i),(ii),(iii) — low-rise: 50 percent of ground floor units. Multi-storey: 10 percent of total units. Hotels: 10 percent of guest rooms	GAP: CHECKLIST	Code Percentage scoping the checklist never asks about.
<code>scope.existing.achievable</code>	not asked	3.2.3, 4.2.2(a) — existing buildings modified to an achievable extent within economic capacity	GAP: CHECKLIST	Code EXISTING Softens findings for existing buildings; affects recommendation wording, not the threshold.
Street furniture				
<code>furniture.rest.intervals</code>	not asked	5.2.13(iii) — resting facilities at intervals between 100 m and 200 m, adjacent to but outside the accessible route	GAP: CHECKLIST	100 to 200 m EXTERIOR Metric in an otherwise imperial Code.
<code>furniture.contrast</code>	not asked	5.2.13(ii) — textural and colour changes in floor surface to identify street furniture	GAP: CHECKLIST	Code EXTERIOR
Public toilets				
<code>toilet.public.outdoor</code>	sector category exists but no items	5.2.14 — at least one unisex accessible toilet per public toilet location, with wash basin, European WC, grab bars, running water, workable illumination; large enough for one wheelchair user plus attendant of either gender	GAP: CHECKLIST	Code EXTERIOR Public Toilet is one of the twelve sectors but the checklist provides no dedicated items.

3 Sign-off

Role	Name	Signature	Date
Prepared by			
Access consultant review			
Approved for use			

No row in this table may be used to generate an issued finding until the access consultant review above is signed.