Bolometer Tuning Summary

HWMap Name: Hwm

HWMap Path: Not Available
Date: Sun Aug 6 21:34:32 2017

2 combs successfully tuned, 0 combs failed to tune

Full Results: Tunings

Total Bolos Attempted: 116

Total Zeroed at start: 0

Total Tuned: 114
Total Latched: 2
Total Unfinished: 0

Readout Module	Bolos (attempted)	Disabled At Start	Tuned	Latched	Unfinished
0028/1/3	60	0	58	2	0
0028/2/4	56	0	56	0	0

Failed Combs

Comb	Failure reason
------	----------------