E3

4

1.00


Experiment settings

Mask

Peak picking

Geometry fitting

Cake & integration



How to

The target is to identify at least 2 rings by location and number. Then to extract all peaks automatically.

Click on the ring you want to select. Usually it is the first one, else update it's number in the list of the picked rings.

Use the recalibration tool to extract more peaks automatically.

Pick peaking

Mode:

a





Picked rings –

Name

Peaks Ring number

177

132

146

d

Redo

Recalibrate

Max rings to extract:

Undo extract rings

Number of peak per degree:

Extract

X: -127.3504

Y: 763.4291

Value: n/a

Next >