



Programmable Electronic Mining Systems: Best Practice Recommendations (in Nine Parts): Part 9: 7.0 Independent Functional Safety Assessment Guidance

By Department of Health and Human Services: Centers for Disease Control and Prevention, National Institute for Occupational Safety and Health (NIOSH)

Bibliogov, United States, 2013. Paperback. Book Condition: New. 246 x 189 mm. Language: English . Brand New Book ***** Print on Demand *****. This report (Independent Functional Safety Assessment Guidance 7.0) is the last in a nine-part series of recommendations and guidance addressing the functional safety of processor-controlled mining equipment. It is part of a risk-based system safety process encompassing hardware, software, humans, and the operating environment for the equipment s life cycle. Figure 1 shows a safety framework containing these recommendations. The reports in this series address the various life cycle stages of inception, design, approval and certification, commissioning, operation, maintenance, and decommissioning. These recommendations were developed as a joint project between the National Institute for Occupational Safety and Health and the Mine Safety and Health Administration. They are intended for use by mining companies, original equipment manufacturers, and aftermarket suppliers to these mining companies. Users of these reports are expected to consider the set in total during the design cycle.



READ ONLINE

Reviews

This book may be really worth a read through, and a lot better than other. It is really basic but excitement inside the 50 % in the pdf. I realized this pdf from my dad and i encouraged this publication to learn.

-- Curtis Bartell

The book is straightforward in study better to comprehend. It is really simplistic but unexpected situations in the fifty percent of the ebook. Its been written in an exceptionally simple way which is simply after i finished reading through this ebook in which basically altered me, affect the way i really believe.

-- Letha Corwin