

01 Operating summary

Line 4 output recovered after maintenance, but two unresolved control checks still constrain the Friday capacity release.

Plant 6 · Line 4 · review window 2026-09-14 through 2026-09-20 · batches L4-260918-A-7741 / B-7742 · owner: Process Engineering.

02 Performance

First-pass yield


96.2%

Unplanned downtime

7.4h


03 Analysis

First-pass yield improved from 94.6% to 96.2% after the valve service. Downtime remains 7.4 hours, above the 6-hour limit. Sample 19 is outside the SPC centerline pattern but inside the product specification; treat this as a process signal for investigation, not a customer defect or capability claim.



SPC Control Chart: 6 rows · X Sample · Y
Measurement · 4 fields

Yield by shift



Line Chart: 4 rows · X Shift · Y Yield · 2 fields

04 Response workflow



AREA / IDENTIFIER	STATUS	OPERATOR
ETCH-08-A / PM-44719	Calibration open	Ed
Line 4 / sample 20	Matched rerun	Pr
Batch L4-260918-B-7742	Release gated	Q

- Measurement system remains within the qualified reference range.

Sample: 30 parts · method: inline metrology ·
source: shift B inspection.

Evidence

Verified

05 Decision

- Keep Friday capacity release conditional

Review

Await pressure calibration, matched sample 20, and Quality sign-off. A point inside specifications can still warrant a control-chart investigation.

06 Next steps

Complete chamber verification and update the runbook.	Active
---	--------

Active

Owner: Equipment Engineering - due next shift
evidence: paired control lot.

Supply-chain holdout · 320 px


01 Overview

The Q4 capacity plan covers baseline demand, but a long-lead actuator constraint leaves the launch buffer exposed.

Northstar launch · weeks 38–45 · supplier
feed closed 2026-09-23 18:00 UTC ·
demand scenario P70 · allocation review for
Operations and Procurement.

02 Performance

Confirmed capacity · W38 to W45



P70 capacity headroom

2.7%


Actuator lead time

116 days

03 Analysis

Confirmed capacity exceeds the P70 baseline by 2.7% in aggregate. Another 27,500 actuator units remain unconfirmed across two suppliers; the 116-day lead time makes that small buffer fragile. Do not treat planned capacity as firm supply until the dated allocation lands.

Demand by week



Line Chart: 8 rows · X Week · Y Demand units
· 4 fields

Confirmed capacity by week



Line Chart: 8 rows · X Week · Y Confirmed
capacity · 4 fields

04 Evidence

Allocation decision path

SUPPLIER / PART	COMMITTED
Northstar Motion / AX-8841	72000
Apex Controls / actuator-22B	54000
Orion Systems / NX-041-REV-C	39000

05 Decision

! Reserve critical actuator supply before releasing the balance At risk

Aggregate headroom hides a concentrated 16-week lead-time constraint. Do not treat unconfirmed supplier allocation as available capacity.

06 Next steps

✓ Next step: reserve 18,000 qualified actuators now, then release the remaining build only after supplier NC-8841 confirms its dated

01 Executive summary

Retention improved for a second quarter, but the public sector renewal gap still threatens FY26 expansion.

FY26 Q1–Q4 close · enterprise and public sector portfolios · constant-currency bookings · renewal cohort excludes acquired accounts.

02 Performance


Constant-currency bookings

14.1 \$M

FY26 renewal rate


92.9%

Renewal rate · Q1 to Q4




03 Analysis

Quarterly retention



Line Chart: 4 rows · X Quarter · Y Retention · 3 fields

Bookings by quarter



Line Chart: 4 rows · X Quarter · Y Bookings · 3 fields

04 Regional evidence

PORTFOLIO	RENEWALS	RATE	EVIDENCE / RISK
Enterprise North	1842	94.1%	Above 91% guarantee
Public Sector West	684	84.7%	Two contracts delayed
Strategic Accounts	213	92.9%	FY26 Q4 close; l

05 Decision

!

Hold public-sector expansion until the renewal gate clears

Two delayed procurement cycles remain unsigned. Keep the current enterprise plan and review those contracts at the next finance checkpoint.

Watch

06 Decision and next step

✓

Next step: keep the enterprise hiring plan, but release the public-sector expansion budget only after the named renewals are signed.


01 Investigation summary

Lot WQ-7314 shows a localized edge-band yield loss after the September 18 ETCH-08 chamber A run.

Wafer WQ-7314 · route R17B · ETCH-08 / chamber A · inline metrology sample 4,812 · paired reference wafer WQ-7298.

02 Performance


Affected vs paired-reference yield



Affected edge-band yield

91.8%

03 Analysis




Wafer Map: 113 rows · X Die X · Y Die Y · 3 fields



SPC Control Chart: 5 rows · X time · Y value · 8 fields

Control versus affected distribution



Box Plot: 16 rows · Measurement Thickness nm · 2 fields

Verified finding

Signal · WQ-7314 edge-band yield is below the paired reference.

Nine lower-right edge-band records average 91.8% versus a 98.0% paired-reference mean. Pressure shift begins after PM-44719; cause remains unconfirmed. Keep the lot contained through endpoint calibration and matched rerun.

Evidence Needs verification

04 Engineering evidence



MEASURE	AFFECTED	REFERENCE	REVIEW
Edge-band yield	91.8%	98.0%	Contain penc
Film thickness	798.0 nm	802.1 nm	Check endpc
Pressure offset	+2.4 kPa	Baseline	Association c

05 Corrective action

Contain WQ-7314 pending chamber requalification

Contain

Do not release the lot from one correlated pressure trace. Verify endpoint calibration and a matched chamber B rerun.


01 Experiment summary

The reminder increased completion, although the week-four uplift is not enough to rule out a novelty effect.

Experiment E-26-041 · eligible new accounts · randomized 1:1 · four weeks · 12,804 assigned · conversion measured within 7 days.

02 Performance

Completion · control to treatment




Treatment completion

24.8%

03 Analysis


Treatment completion rose from 21.1% to 24.8%; control moved from 21.0% to 21.8%. The observed separation is consistent across four weeks, while the support-contact guardrail moved by +0.08 points against a +0.15 limit. This descriptive comparison does not prove the effect will persist after the novelty period.

Conversion by week



Line Chart: 8 rows · X Week · Y Completion · 3 fields

Outcome distribution by cohort



Box Plot: 12 rows · Measurement Completion · 2 fields

04 Experiment evidence

Assignment and guardrail evidence

COHORT	ASSIGNED	COMPLETION	SUPPORT-
Control	6402	21.8%	+0.00 pt
Treatment	6402	24.8%	+0.08 pt

05 Recommendation

!

Extend to 25% exposure with a support-contact stop

Limited rollout

The four-week signal is promising but does not establish persistence. Stop if support-contact change exceeds +0.15 points.