


01 Investigation summary

Affected lot L2407 shows a localized die-level yield loss after ETCH-08 chamber A processing. Contain the lot until the chamber check and paired reference run confirm

Lot L2407 · ETCH-08 chamber A · affected die compared with a paired reference · release held for verification.

02 Engineering evidence



EVIDENCE	AFFECTED	REFEREN
Yield distribution	94.2%	98.6%
Affected lot L2407	94.2%	—
ETCH-08 / A	Pressure +2.1%	Stable

↔ Scroll right for more columns. Use Right Arrow, End, or swipe.


03 Corrective action

Contain lot L2407 through chamber requalification

Contain

Release only after chamber A and the paired reference run confirm recovery.

04 Analysis



Coordinates X - 0-8 · Y - 0-8

Wafer Map: 81 rows · X Die X · Y Die Y · 3 fields



SPC Control Chart: 4 rows · X time · Y value · 8 fields

Control versus affected distribution



Box Plot: 6 rows · Measurement Yield · 2 fields

Verified finding

Finding · chamber A pressure drift aligns with the L2407 yield excursion.

Affected yield is 94.2% versus 98.6% reference.

05 Performance

Affected versus reference yield

Before
98.6 %

After
94.2 %



Affected yield

94.2%

Delta -4.4

Target 95%


01 Operating summary

Shift B recovered yield after chamber maintenance. Keep the recipe locked through the next paired-lot check and hand off the evidence to Quality and

Line 4 · shifts A–C · chamber A controls · capacity release review.


02 Analysis

Yield by shift



Line Chart: 3 rows · X Shift · Y Yield · 2 fields

SPC Control Chart · computed control limits · specifications shown



LCL: 93.474

SPC Control Chart: 5 rows · X Time · Y Measurement · 4 fields

Yield recovered from 94.1% on shift A to 95.0% on shift C, while the control sample remains within specification. Keep the recipe locked until the next paired-lot check closes the two open items.

03 Response workflow



TOOL	CHAMBER	MEASURE	OWNER
ETCH-08	A	Pressure	Equipment
ETCH-07	C	Flow	Process E
MET-02	B	Yield	Quality

↔ Scroll right for more columns. Use Right Arrow, End, or swipe.

Measurement system remains within the qualified reference range.

Sample: 30 parts · method: inline metrology · source: shift B inspection.

Evidence

Verified

04 Decision

Hold added capacity until the paired-lot check closes

Keep the recipe locked and attach the next-shift control evidence.

Review

05 Next steps

Complete chamber verification and update the runbook.

Active

Owner: Equipment Engineering · due next shift · evidence: paired control lot.

06 Performance

First pass yield

95%

Delta 0.9

Target 96%

Unplanned downtime

8.3 h

Delta -1.7

Target 6 h