

KEYSTONE SUBSURFACE INSPECTION

DISTRIBUTION MAIN CONDITION ASSESSMENT

Report reference: CA-2025-0130

Date of inspection: 2025-02-03

Inspector: M. Okonkwo, P.E.

Client: Three Rivers Water Authority

1. SCOPE

Visual and limited non-destructive assessment of distribution main segment WM-1700, located on Negley Avenue in the Shadyside area of the PZ-HL2 pressure zone. The segment is a 24-inch cast iron main of approximately 277 ft, originally installed in 1912.

2. METHOD

Access was obtained by test pit at one location. The exposed section was cleaned and examined visually. Wall thickness was assessed by ultrasonic spot readings where surface condition permitted. No internal inspection was performed.

3. OBSERVATIONS

Sustained leakage at the joint with visible washout of surrounding bedding material.

No active leak observed. Soil at pipe depth was damp with poor drainage.

4. FINDING

Condition classification: SEVERE

Primary observation: joint leakage

5. RECOMMENDATION

Prioritise this segment for replacement planning. Re-inspect within 12 months if replacement cannot be scheduled.

This assessment reflects the condition of the exposed section only and should not be taken as representative of the entire segment.