LEAN SIX SIGMA — COURSE ASSESSMENT

10 Multiple Choice Questions & Answer Key

---

1. What is the primary focus of the Lean methodology?

A) Reducing variation
B) Eliminating waste and improving flow
C) Increasing inspection frequency
D) Implementing software tools

Answer: B) Eliminating waste and improving flow

2. What does DMAIC stand for in Six Sigma?

A) Define, Measure, Analyze, Improve, Control
B) Design, Model, Assess, Implement, Check
C) Develop, Manage, Analyze, Inspect, Control
D) Define, Monitor, Adjust, Integrate, Calculate

Answer: A) Define, Measure, Analyze, Improve, Control

3. How many Defects Per Million Opportunities (DPMO) corresponds to a 6 Sigma performance level?

A) 66,807
B) 6,210
C) 233
D) 3.4

Answer: D) 3.4

4. Which of the following is NOT one of the traditional 8 Wastes (TIMWOODS) in Lean?

A) Transportation
B) Overproduction
C) Profitability
D) Defects

Answer: C) Profitability

5. What tool is used to map high-level processes showing Suppliers, Inputs, Process, Outputs, and Customers?

A) SIPOC Diagram
B) Pareto Chart
C) Fishbone Diagram
D) Control Chart

Answer: A) SIPOC Diagram

6. What is the main purpose of a Fishbone (Ishikawa) Diagram?

A) Tracking project schedules
B) Identifying potential root causes of a problem
C) Calculating statistical standard deviation
D) Setting product pricing

Answer: B) Identifying potential root causes of a problem

7. The 80/20 rule is associated with which Quality tool?

A) Scatter Plot
B) Histogram
C) Pareto Chart
D) Value Stream Map

Answer: C) Pareto Chart

8. What does the Japanese term "Poka-Yoke" mean in Lean manufacturing?

A) Continuous improvement
B) Mistake-proofing / Error-proofing
C) Visual workplace
D) Just-in-Time scheduling

Answer: B) Mistake-proofing / Error-proofing

9. In 5S methodology, what are the 5 steps in order?

A) Sort, Set in order, Shine, Standardize, Sustain
B) Select, Systematize, Sweep, Sanitize, Supervise
C) Start, Shape, Scrub, Simplify, Support
D) Sort, Secure, Shine, Solve, Sustain

Answer: A) Sort, Set in order, Shine, Standardize, Sustain

10. During which phase of DMAIC are solutions implemented to address root causes?

A) Measure
B) Analyze
C) Improve
D) Control

Answer: C) Improve