Apply all tool on image then reset 1. Image Tooks on variety of madalities (- Test on multiple modalities (CT, P1, US, XA, MR) - Create report ledit report (. 2. Doumen viewer - Edit type I name Attach type of report - can wate from template Auto load report as setting 3. Rapid - Image Vener - Apply all tool (teston name (T, US, MR) - Fundian of Next France Previous Frame/Next Fameset /Previous Frameset workOk - Run HR MPR then apply tool noise > Messaging on Knode on Click Hessaging < touch mode -) 1_ on touch mode Check button on MPR tool. Drag and drop study to worklist (past, convert, future) q. Scheduler/Korklist Drag aprid drop appointement between resource Create block time - Check funtion when right click an scheduler create new worklist / Change workhist Suith Suitch worklist Cus farnize nor Khist