

Site #4344: AVONDALE #1B, Jefferson, Louisiana

Entergy Louisiana

23.6 MW




Fiber Infrastructure

|                           |                                                  |
|---------------------------|--------------------------------------------------|
| Fiber Carrier             | AT&T, Cox Communications, Lumen, Zayo, EarthLink |
| Distance to Backbone      | ~2–5 mi                                          |
| Fiber Lateral Required    | ~2–4 mi                                          |
| Number of Upstream Routes | 3–4                                              |
| Upstream Capacity         | 1–4 Tbps                                         |
| Nearest Carrier Facility  | New Orleans CBD (~12 mi east)                    |

Nearest Substation: ~ 2 Miles


Power Infrastructure Capacity






Site #4344: AVONDALE #1B, Jefferson, Louisiana

SITE CHANGE DETECTION & BASELINE MONITORING



| ACCESS ROUTE & SITE CONDITION ASSESSMENT |                      |            |
|------------------------------------------|----------------------|------------|
| Assessment Item                          | Status               | Risk Level |
| Access Road Condition                    | Fair                 | ●          |
| Road Obstructions                        | Moderate             | ●          |
| Post-Storm Accessibility                 | Partially Accessible | ●          |
| Gate Access Visibility                   | Clear                | ●          |
| Parking / Staging Area                   | Available            | ●          |
| Overall Access Status: LIMITED ACCESS    |                      |            |

| VEGETATION & ENCHROACHMENT MONITORING |              |            |
|---------------------------------------|--------------|------------|
| Monitoring Category                   | Observation  | Risk Level |
| Vegetation Growth (25 ft)             | Clear (0%)   | ●          |
| Vegetation Growth (50 ft)             | High (40.4%) | ●          |
| Vegetation Growth (100 ft)            | High (46.3%) | ●          |
| Fence Line Enchroachment              | None         | ●          |
| Access Road Overgrowth                | Critical     | ●          |
| Tree Canopy Expansion                 | High         | ●          |
| Fire Fuel Accumulation                | High         | ●          |
| Vegetation Risk Level: High           |              |            |




- SITE CHANGE HIGHLIGHTS
- No significant changes to the primary site infrastructure were observed between the baseline and current imagery.
  - No visible missing or damaged antenna-related assets were identified from the available imagery.
  - Additional unidentified objects were observed within the site compound compared to the baseline imagery.
  - Vegetation encroachment is present within the 50-ft assessment area and may require routine maintenance.


Overall Monitoring Result: Limited Access with High Vegetation Risk



Evidence on the Ground



Nearest Parking: ~ 0.5 Miles



Veg. Encroachment



Gate Accessibility