On crafts engaged on voyages in sea areas A3 and A4, the availability should be ensured by using acombination of at least two methods such as duplication of equipment, shore-based maintenance or at-sea electronic maintenance capability, as may be approved by the Administration, taking into account the I'ecommendations of the Organization"""". However, crafts operating solely between ports where adequate facilities for shore-based maintenance of the radio installations are available and provided no journey between two such ports exceeds six hours, then the Administration may exempt such crafts from the requirement to use at least two maintenance methods. For such crafts at least one maintenance method should be used. * Refer to the Recommendation on general requirements for shipborne radio equipment forming part of the global maritime distress and safety system and for electronic navigational aids , adopted by the Organization by resolution A.694(11). ** Administrations should take account of the Recommendations on radio maintenance guidelines for the Global Maritime Distress and Safety System - and for electronic navigational aids , adopted by the Organization by resolution A.694(11). ** Administrations should take account of the Recommendations on radio maintenance guidelines for the Global Maritime Distress and Safety System (GMDSS) related to sea areas A3 and A4 , a.dopted by the Organization by resolution A.102(11) W/1681n/pp/EWP RESOLUTION MSC.36(63) (adopted on 20 May 1994) ADOPTION OF THE INTERNATIONAL CODE OF SAFETY FOR HIGH SPEED CRAFT 14.14.9 14.15 14.16 MSC 62/23/Add.2 ANNEX 18 Page 145 While all reasonable steps should be taken to maintain the equipment in efficient working order to ensure compliance with all the functional requirements specified in 14.4, malfunction of the equipment for providing the general radiocommunications, required by 14.4.8, should not be considered as making acraft unseaworthy or as areason for delaying the craft in ports where repair facilities are not readily available, provided the craft is capable of performing all distress and safety functions. Radio pers~ Every craft should carry personnel qualified for distress and safety radiocommunication purposes to the satisfaction of the - not readily available, provided the craft is capable of performing all distress and safety functions. Radio pers~ Every craft should carry personnel qualified for distress and safety radiocommunication purposes to the satisfaction of the Administration. The personnel should be holders of certificates specified in the Radio Regulations as appropriate, anyone of whom should be designated to have primary responsibility for radiocommunications during distress incidents. Radio records Arecord should be kept, to the satisfaction of the Administration and as required by the Radio Regulations, of all incidents connected with the radiocommunication service which appear to be of importance to safety of life at sea. W/l687n/pp/EWP RESOLUTION MSC.36(63) (adopted on 20 May 1994) ADOPTION OF THE INTERNATIONAL CODE OF SAFETY FOR HIGH SPEED CRAFT MSC 62/23/Add.2 ANNEX 18 Page 146 15.1 15.1.1 15.1. 2 15.1. 3 15.1. 4 15.2 15.3 15.3.1 15.3.2 15.3.3 15.3.4 CHAPTER 15 - OPERATING COMPARTMENT LAYOUT Definitions "Operating area" is the operating compartment and those parts of the craft on both sides of, and close to, the operating compartment - 15.1. 4 15.2 15.3 15.3.1 15.3.2 15.3.3 15.3.4 CHAPTER 15 - OPERATING COMPARTMENT LAYOUT Definitions "Operating area" is the operating compartment and those parts of the craft on both sides of, and close to, the operating compartment which extend to the craft'sside. "Workstation" is aposition at which one or several tasks constituting aparticular activity are carried out. "Docking workstation" is aplace equipped with necessary means for docking the craft. "Primary controls" are all control equipment necessary for the safe operation of the craft when it is underway, including those required in an emergency situation. General The design and layout of the compartment from which the crew operate the craft should be such as to permit operating crew members to perform their duties in acorrect manner without unreasonable difficulty, fatigue or concentration, and to minimize the likelihood of injury to operating crew members in