"3.2 These messages should be stored until readout and should be erased 48 hours after their reception . " Modify the second sentence of paragraph 4 of Part D, the Annex, as follows : "4 ..... The means for initiating adistress alert should be as prescribed in 2.5 to 2.7 of Part A." IEC 1162 I:\MSC \68\23-Add .l RESOLUTION MSC.68(68) (adopted on 6 June 1997) ADOPTION OF AMENDMENTS TO PERFORMANCE STANDARDS FOR SHIPBORNE RADIOCOMMUNICATION EQUIPMENT MSC 68/231 Add. 1 ANNEX 10 Page 4 ANNEX 3 AMENDMENTS TO RESOLUTION A.806(19) - PERFORMANCE STANDARDS FOR MF/HF RADIO INSTALLATIONS CAPABLE OF VOICE COMMUNICATION NARROW-BAND DIQECT-PRINTING AND DIGITAL SELECTIVE CALLING Modify paragraphs 2.4, 2.5 and 2.6 of Part D, the Annex, as follows : ".4 means to display, in plain language with aminimum of 160 characters in two or more lines, the information contained in areceived call; - ".4 means to display, in plain language with aminimum of 160 characters in two or more lines, the information contained in areceived call; .5 facilities to automatically update the ship'sposition and the time at which the position was determined from asuitable electronic position-fixing aid which may be an integral part of the equipment. For equipment which does not have an integral position-fixing aid, such facilities should include asuitable interface conforming to the appropriate international standard; 1 .6 means for manual entry of position information and the time at which the position was determined; and" Add new paragraph 2.7 of Part D, the Annex : ".7 means to activate an alarm when no position data is received from the electronic position-fixing aid or, in the case of manual input, the position information is over 4 hours old. Any position information not updated for more than 2312 hours should be erased. II - position-fixing aid or, in the case of manual input, the position information is over 4 hours old. Any position information not updated for more than 2312 hours should be erased. II Modify paragraph 3.2 of Part D, the Annex, as follows: ".3.2 These messages should be stored until readout and should be erased 48 hours after their reception . II Modify the second sentence of paragraph 4 of Part D, the Annex, as follows: "4 ..... The means for initiating adistress alert should be as prescribed in 2.5 to 2.7 of Part A" IEC 1162 I:\MSC\68\23-Add.l RESOLUTION MSC.68(68) (adopted on 6 June 1997) ADOPTION OF AMENDMENTS TO PERFORMANCE STANDARDS FOR SHIPBORNE RADIOCOMMUNICATION EQUIPMENT ANNEX 4 MSC 68/23/ Add . 1 ANNEX 10 Page 5 AMENDMENTS TO RESOLUTION A.807(19) - PERFORMANCE STANDARDS FOR INMARSAT-C SHIP EARTH STATIONS CAPABLE OF TRANSMITTING AND RECEIVING DIRECT-PRINTING COMMUNICATIONS Modify papragraph 3.8 of the Annex, as follows: - INMARSAT-C SHIP EARTH STATIONS CAPABLE OF TRANSMITTING AND RECEIVING DIRECT-PRINTING COMMUNICATIONS Modify papragraph 3.8 of the Annex, as follows: "3.8 Facilities should be provided to automatically update the ship'sposition and the time at which the position was determined from asuitable electronic position-fixing aid which may be an integral part of the equipment. For equipment which does not have an integral electronic position-fixing aid, such facilities should include asuitable interface conforming to the appropriate international standard. I" Add'new paragraphs 3.9 and 3.10 to the Annex, as follows: "3.9 Provisions should also be made for manual entry of position information and of the time at which the position was determined. 3.10 An alarm should be activated when no position data is received from the electronic position-fixing aid or, in the case of manual input, the position information is over 4 hours old. Any positio