inspection every 4
months.
When recommended
by the AFS
manufacturer, more
frequent proactive
cleaning activities
could be
implemented
between
inspections.>
<EXAMPLE>
<Evaluate the need
for a potential
improvement of the
AFS selection prior
to the next
dry-docking.>
<EXAMPLE>
<Deviation from
temperature range
specifications
acceptable for the
AFS>
<EXAMPLE>

---CHUNK---

SOURCE: MEPC.378%2880%29.pdf
for a potential
improvement of the
AFS selection prior
to the next
dry-docking.>
<EXAMPLE>
<Deviation from
temperature range
specifications
acceptable for the
AFS>
<EXAMPLE>
<Incidental deviations
should be evaluated
for potential biofouling
impact.
Continuous or regular
deviations, or
deviations not
rectified, should lead
to contingency
actions.>
<EXAMPLE>
<Shorter inspection
interval with

inspection every 4
months.
When recommended
by the AFS
manufacturer, more
frequent proactive
cleaning activities
could be
implemented
between
inspections.>
<EXAMPLE>
<Evaluate the need
for a potential
improvement of the
AFS selection prior
to the next
dry-docking.>

Biofouling risk
parameters to
monitor

---CHUNK---

SOURCE: MEPC.378%2880%29.pdf
MINIMIZE THE TRANSFER OF INVASIVE AQUATIC SPECIESMEPC 80/17/Add.1
Annex 17, page 48

I:\MEPC\80\MEPC 80-17-Add.1.docx
Biofouling risk
parameters to
monitor
Evaluation of a
deviation including
deviation limit of the
risk parameter
Contingency
actions
Long-term actions
<EXAMPLE>
<Deviation from the
maintenance/service
regime of the AFC>
<EXAMPLE>
<If the maintenance

and service time, specified by the manufacturer, is exceeded, the risk of biofouling is elevated, and contingency actions should be implemented>.
<EXAMPLE>
<An inspection should be carried out for the relevant area. Maintenance or repair should be performed at earliest possible opportunity.>
<EXAMPLE>
<Regular maintenance and repair (e.g.) may be necessary actions for proper protection by the AFC. Evaluate the need to update maintenance programme.>
<EXAMPLE>
<AFC damage>
<EXAMPLE>
<Failure caused by mechanical damage to the AFC may result in higher risk of

---CHUNK---

SOURCE: MEPC.378%2880%29.pdf
by the AFC. Evaluate the need to update maintenance programme.>
<EXAMPLE>
<AFC damage>
<EXAMPLE>
<Failure caused by mechanical damage to the AFC may result in higher risk of biofouling in the areas affected, if not rectified within reasonable time.

The damage should be evaluated for potential biofouling accumulation.>
<EXAMPLE>
<An inspection should be carried out for the relevant area. Repair should be performed at earliest opportunity.
More frequent inspections of damaged area should be implemented until a repair is undertaken.>

<EXAMPLE>
<Deviation from the maintenance/service regime of the MGPS>