AMENDMENTS TO THE CODE FOR THE CONSTRUCTION AND EQUIPMENT
OF MOBILE OFFSHORE DRILLING UNITS, 2009
(2009 MODU CODE)

CHAPTER 10
LIFE-SAVING APPLIANCES AND EQUIPMENT

1 Paragraphs 10.14, 10.14.1 and 10.14.2 are replaced by the following:

"10.14 [Reserved*]

_____
* The provisions related to radio life -saving appliances were relocated under chapter 11 (refer to resolution MSC.506(105). Paragraph 10.14 was intentionally left blank to avoid renumbering of existing paragraphs."

CHAPTER 11
RADIOCOMMUNICATION AND NAVIGATION

2 The text of chapter 11 is replaced by the following:

11.1 General

The purpose of this chapter is to provide minimum provisions for navigation equipment and for distress and safety radiocommunications between mobile offshore drilling units, including associated survival craft, and coast stations, ships and supporting aircraft.

11.2 Training

SOURCE: MSC.506(105).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
associated survival craft, and coast stations, ships and supporting aircraft.

11.2 Training

Training in the use of IMO Standard Marine Communication Phrases should be provided to personnel responsible for radio communications.1

_____
1 Refer to IMO Standard Marine Communication Phrases (resolution A.918(22)).

11.3 Self-propelled units

Each unit should comply with the applicable provisions concerning radio stations for cargo ships in SOLAS chapter IV.2

_____
2 All requirements of SOLAS chapter IV referring to from the position from which the ship is normally navigated should be appl ied as meaning from the position the MODU is normally navigated.

11.4 Non-self-propelled units under tow

11.4.1 The provisions for non-self-propelled units under tow when manned depend upon the radio installations fitted in the towing ship, as set out in paragraphs 11.4.2 and 11.4.3.

RESOLUTION MSC.506(105) (adopted on 28 April 2022)

SOURCE: MSC.506(105).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
radio installations fitted in the towing ship, as set out in paragraphs 11.4.2 and 11.4.3.

11.4.2 In cases where the towing ship complies fully with all applicable requirements concerning radiocommunications for ships prescribed in SOLAS chapter IV, the unit under tow when manned should:

.1 be fitted with VHF facilities as required by SOLAS regulations IV/7.1.1 3 and 7.1.2 and with MF facilities as required by regulations IV/9.1.1 and 9.1.2;

.2 be fitted with an EPIRB as required by SOLAS regulation IV/7.1.5; and

.3 be fitted with receiver(s) capable of re ceiving MSI and SAR related information throughout the entire voyage in which the unit is engaged in accordance with SOLAS regulation IV/7.1.4.

SOURCE: MSC.506(105).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
information throughout the entire voyage in which the unit is engaged in accordance with SOLAS regulation IV/7.1.4.

11.4.3 In cases where the towing ship does not comply fully with the applicable requirements concerning radiocommunications for ships prescribed in SOLAS chapter IV, the unit under tow when manned should comply with all the applicable provisions concerning radiocommunications prescribed in SOLAS chapter IV.3

_____
3 All requirements of SOLAS chapter IV referring to from the position from which the ship is normally navigated should be applied as meaning from a position which is continuously manned and which is controlling the MODU while under tow.

11.5 Units stationary at the site or engaged in drilling operations

11.5.1 Each unit, while stationary at the site, including when engaged in drilling operations,

should comply with all requirements prescribed in SOLAS chapter IV that are applicable to a
---
SOURCE: MSC.506(105).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
should comply with all requirements prescribed in SOLAS chapter IV that are applicable to a ship sailing through the same area.4 Each unit should also report its position to the relevant World-Wide Navigational Warning Service (WWNWS) NAVAREA Coordinator when arriving on-site, in order for a Navigational Warning to be broadcast.5 Additionally, units should inform the NAVAREA Coordinator when departing from that site, in order for the broadcast to be cancelled.

11.5.2 On units which do not have a navigation bridge, it should be possible to initiate transmission of the distress alerts by the radio installation specified in SOLAS regulations IV/10.1.1, 10.1.2 and 10.1.4, as applicable, from a position in an accessible and protected area which is acceptable to the Administration.

11.5.3 If the acoustic noise level in a room fitted with operating controls for radio equipment is so high or could be so high, during particular operating conditions, that it may disturb or
---
SOURCE: MSC.506(105).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
is so high or could be so high, during particular operating conditions, that it may disturb or prevent proper use of the radio equipment, then adequate noise protection should be provided by mechanical or other means, in association with the op erating controls for the radio equipment.

_____

4 All requirements of SOLAS chapter IV referring to from the position from which the ship is normally navigated should be applied as meaning from a position or positions which are continuously manned and which are controlling the MODU while stationary at the site including its drilling operations (i.e. normally the control room).
5 Refer to the World-Wide Navigational Warning Service (resolution A.706(17), as amended).

SOURCE: MSC.506(105).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)
MSC 105/20/Add.1
Annex 13, page 4

I:\MSC\105\MSC 105-20-Add.1.docx

11.6 Radio life-saving appliances

Two-way VHF radiotelephone apparatus

11.6.1 All lifeboats should carry a two-way VHF radiotelephone apparatus.

11.6.2 At least two two -way VHF radiotelephone apparatuses should be available on the MODU, so stowed that they can be rapidly placed in any liferaft. 6 All two -way VHF radiotelephone apparatuses should conform to performance standards not inferior to those adopted by the Organization.

_____

6 The two -way VHF radiotelephone apparatus required by 11.6.2 may fulfil or partially fulfil the requirements of SOLAS regulations IV/7.2, 7.3 or 7.4, as applicable.

Search and rescue locating device

11.6.3 All lifeboats should carry one radar SART or AIS-SART.

11.6.4 At least two radar SARTs or AIS-SARTs should be available on the MODU, so stowed

---

SOURCE: MSC.506(105).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf

11.6.4 At least two radar SARTs or AIS-SARTs should be available on the MODU, so stowed that they can be rapidly placed in any liferaft. 7 All SARTs or AIS -SARTs should conform to performance standards not inferior to those adopted by the Organization.

_____

7 The radar SARTs or AIS-SARTs required by 11.6.4 may fulfil the requirements of SOLAS regulations IV/7.1.3, 7.2, 7.3 or 7. 5, as applicable.

11.7 Helicopter communications

In order to ensure communication with helicopters, MODUs should carry an aeromobile VHF radiotelephone station complying with the relevant requirements of ICAO 8 and suitable for